

224-9822
Ext. 155

CERTIFICATE OF COMPLIANCE
INSPECTION REPORT

ADDRESS: 3232 W. BRADLEY RD.

OWNER: _____

INSPECTION DATE: 12-9-97 10am

H.V.A.C. *Provide proper Combustion Air For Gas Appliances
in Confined Space As per manuf. Specifications.*

Furnace/Boiler - Proper Installation Yes No *Combustion Air.*

* Comments: Lennox Gas Forced Air Furnace
by IDEAL. 9-897

Air Conditioning - Proper Installation Yes No *Room Area 14'-6" x 10'-6"
x 7'-6"*

Comments: Central. *Hall 3' x 10'*

Wall/Space Heater - Proper Installation Yes No

Comments: N/A

Fireplace - Proper Installation Yes No

Comments: _____

Wood Burning Appliance - Proper Installation Yes No

Comments: N/A

Other - Proper Installation Yes No

* Comments: Replace & Secure Gas Chimney,
Cleanout Door & Frame.

10000
1140
1160
288

BUILDING

Basement Remodeling - Proper Installation Yes No

Comments: _____

Screen/Patio Room - Proper Installation Yes No

Comments: N/A

Misc. Remodeling - Proper Installation Yes No

Comments: _____

Garage - Proper Installation Yes No

Comments: Attached. 2 cars

Stairways - Proper Installation Yes No

Comments: _____

Handrails - Proper Installation Yes No

Comments: _____

Guardrails - Proper Installation Yes No

Comments: N/A

Basement Bedroom(s)

Comments: Yes. Remodeled 1997. Egress Windows.

Polystyrene Insulation

Comments: D/A

Other - Proper Installation Yes No

* Comments: EGRESS WINDOW AREA. WALLS MISSING
ALUM. GRATES AS PER CONTRACTOR. CURRENTLY COVERED
W/PLYWOOD - GRADE AROUND AREA WILL NOT
FIRE CODE BACKFILL COMPLETELY.

Smoke Detectors - Proper Installation Yes No

* Comments: BATTERIES IN FURNACE ROOM DET.

Fire Wall (Garage; breezeway) - Proper Installation Yes No

* Comments: PATCH & REPAIR HDS IN GARAGE
FIRE WALL - COVER ATTIC ACCESS PANEL W/ 5/8"
TYPE X IRON WALL.

Other - Proper Installation Yes No

Comments: _____

PLUMBING

Basement Toilet Room - Proper Installation Yes No

Comments: FULL BATH W/ SHOWER

Water Heater (Gas) (Electric) - Proper Installation Yes No

Comments: (2) STATE GAS WATER HTES
(35,500) BTU EACH

Bar Sink /Darkroom Sink- Proper Installation Yes No

Comments: D/A

Dishwasher - Proper Installation Yes No

Comments: _____

Fixtures Added - Proper Installation Yes No

Comments: N/A

Damaged Fixtures

Comments: _____

Other - Proper Installation Yes No

Comments: _____

BROWN DEER CODE

Well System - Working Abandoned

Comments: N/A

Swimming Pool - Proper Installation Yes No

Comments: N/A

Sump Pump - Yes No

Comments: _____

Address Numbers - Conforming Yes No

* Comments: None Provide Visible Address #'s

Other - Proper Installation Yes No

Comments: _____

ELECTRIC

Garage Wiring - Proper Installation Yes No

Comments: _____

Garage Door Opener - Proper Installation Yes No

Comments: _____

Basement Remodeling - Proper Installation Yes No

Comments: _____

Air Conditioning/Heating Units - Proper Installation Yes No

Comments: _____

Patio/Screen Room - Proper Installation Yes No

Comments: _____ *JPA*

Lamp Post/Exterior Lighting - Proper Installation Yes No

Comments: _____

Eds Cas.
Dryer/Range - Proper Installation Yes No

Comments: _____

