COMPLIANCE APPLICATION

FEE TO ACCOMPANY APPLICATION

VILLAGE OF BROWN DEER

4800 West Green Brook Drive Brown Deer, Wisconsin 371-3030 (FAX) 371-3045

Make Check Payable To: VILLAGE OF BROWN DEER

OFFICE USE ONLY INSPECTION DATE & TIME

21/2× 11 D.1=	INSPECTION DATE & TIME
ADDRESS 3435 W. Pelican Ln	Wed July 9:3
TYPE OF OCCUPANCY:X SINGLE FAMILYTWO-FAMILY	FEE CHECK/CASH
CURRENT OWNER: Linda + Chris Bucton	\$150.00 PAIN CR#4
ADDRESS: 3435 W. Pelican Ln P	Drawn Deer WI 5320
TELEPHONE: (444) 305-3606	STATE ZIP
AGENT FOR OWNER:TELE	PHONE: ()
ADDRESS:	
NO. STREET CITY	STATE ZIP
A CERTIFICATE OF COMPLIANCE WILL NOT BE ISSUED UNLESS REPAIRS ORDERED BY THE BUILDING CANNOT BE REPUIDED.	GINSPECTOR ARE PERFORMED. FEE
Anda Breton 6/20/05	-
SIGNATURE OF APPLICANT DATE	×

DATE

COMPLIANCE APPLICATION

VILLAGE OF BROWN DEER

4800 West Green Brook Drive Brown Deer, Wisconsin 371-3030 (FAX) 371-3045

FEE TO ACCOMPANY APPLICATION

Make Check Payable To: VILLAGE OF BROWN DEER

	371-3030 (FAX) 371			TCE USE ONLY TON DATE & TIME
ADDRESS 3435 W. PELL	CANLANE, Beow	N DEER NI 5320	FEE TUES.	Feb. 13 3p.m.
TYPE OF OCCUPANCY: X SINGI CURRENT OWNER: FREDERICE P.	LE FAMILY	I WO-FAMILY	\$50.00	#3125
ADDRESS: 3435 W.	PELICAN LANE,	BROWN DEER,	WE STATE	53209 ZIP
TELEPHONE: (414)	355-9485			
AGENT FOR OWNER:		TELEPHON	IE: ()	
ADDRESS:NO.	STREET	CITY	STATE	ZIP
A CERTIFICATE OF COMPLIANCE WILL NOT BE IS CANNOT BE REFUNDED.	SUED UNLESS REPAIRS ORDER	ED BY THE BUILDING INSP	ECTOR ARE PE	RFORMED. FEE
Freduck P. m	ai s	7-1-01		
SIGNATURE OF APPLICA	NT	DATE		

APPLICATION FOR PERMIT

TC	THE INSPECTOR OF BUILDINGS: VILLAGE OF BROWN DEER, WIS September 11 , 19 76
	The undersigned hereby applies for a permit to remodel and addfamily room according to the following statement:
	Owner Rev. Frederick P. Mai Address 3135 W. Pelican Lane Address 355-9485
	Cost 2,000 Fee 5, 55 Lot Nine (9) Block Two (2) Subd. Collins Meadow
4.	Kind of building (factory, shop, store, dwelling?) Dwelling
	Class of construction FRAME To be occupied by owner
6.	Name of contractor Frederick P. Maiowner & residents 3/135 W. Pelican Lane
7.	Name of ArchDesignEng. Steve Peterman Address 11625 N. Austin, Mequon, Wis.
8.	Is building old or new or being remodeled? Approximately 25 years old
9.	(State in detail kind of occupancy or work to be performed.) Mention alterations, replacements, etc. The existing breezeway, between the house and the garage, is to be enlarged
	and turned into a family room for year-round use. The existing breezeway is 11' X 11'it will be enlarged to 11' X 22'.
_	
and	It is Hereby Agreed between the undersigned, as owner, his agent or servant, and the Village of Brown Deer, that for and in consideration of the premises of the permit to construct, erect, alter or install and the occupancy of building as above described, to be issued and granted by the Building Inspector, that

It is Hereby Agreed between the undersigned, as owner, his agent or servant, and the Village of Brown Deer, that for and in consideration of the premises and of the permit to construct, erect, alter or install and the occupancy of building as above described, to be issued and granted by the Building Inspector, that the work thereon will be done in accordance with the descriptions herein set forth in this statement, and as more fully described in the specifications and plans herewith filed; and it is further agreed to construct, erect, alter or install and occupy in strict compliance with the ordinances of the Village of Brown Deer, and to obey any and all lawful orders of the Building Inspector of the Village of Brown Deer, and all State Laws relating to the construction, alteration, repairs, removal and safety of buildings and other structures and permanent building equipment.

NAME

Checked by

Address 31,35 W. Pelican Lane



Village of Brown Deer

4800 W. Green Brook Dr. **Brown Deer, WI 53223** 414-371-3030 / Fax 414-371-3045

PE 18 _ 0216

PERMIT NO:

(PLEASE TYPE OR PRINT WITH BALL POINT PEN)

ELECTRICAL PERMIT APPLICATION

<u> </u>	2011e & TWO Fai	inity Commercial					
Project Address: 3435 1) Pelica	n Ln						
Project Address: 3435 W. Palico Owner: (Print Name)	Owner Telephone: 414-446-8567						
Mailing Address:		City		ate Zip)		
Tellane Halle.		Telephone:					
(If not owner occupied)		Contractor Tolophore					
Electrical Contractor: JSI Electric		Contractor Telephone: 262-781-	363	(
Address: W28259 Trowbridge	Trail	Master Electrician: (Signature)	11.	Uh -	/		
City	Zip	Print Name:					
Hartland Wi	53029			schen			
Electrical Contractor No: 1099775	Expires: 6/28 202\	Master License No: 160427	Ex	pires:	6/30/	aa	
7071713			1	attents.		44	
Estimated Cost of Job \$366 Go	No. Descri		Qty	Fees	Dollars	Cents	
Cost of Job \$ Job Oc	Switches, receptacles & de	evices		\$.50			
Buildings 🔀 Residential	Incandescent lighting fixtu	ures—per lamp		\$.50			
□ Commercial	3. Fluorescent lighting fixture	es—per lamp		\$.50			
☐ Industrial	4. H I D lighting, etc.—per fix	xture	<u></u>	\$ 6.00			
□ New Construction □ Additional Rooms	5. 30 amp outlets & larger or	utlets (ranges, ovens, dryers)		\$ 6.00			
Remodeling	6. Garbage disposal			\$ 6.00			
□ New Occupancy	7. Dishwasher			\$ 6.00			
Describe Scope of Work:	8. Water Heater			\$ 6.00			
bescribe scope of Work.	9. Motors (per h.p. or fraction thereof)			\$.70			
	10. Transformers, generators	s, rectifiers (per KW & U.P.S. systems)		\$.70			
	11. Automatic heating equipment (furnaces, boilers)		/	\$ 7.50	7	50	
Leplacement	12. Electric heating equipment (per unit)			\$ 4.00			
Replacement Furnace &	13. Air conditioner, refrigeration units and compressor			\$ 10.00	10	00	
A/C	14. Dimmer and timing device	es, G.F.C.I. devices		\$ 4.00			
	15. Feeder or sub feeder—sub-panel			\$ 15.00			
	16. Wireways, bus ways, und	ler floor raceways, aux. gutters/ft.		\$.50			
	17. Strip & track lighting, plug-in strip & similar sys./ft.			\$.50			
	18. Signs, illuminated			\$ 30.00		-	
	19. Hydromassage bathtub—		<u> </u>	\$ 10.00			
	20. Swimming pools, Jacuzzis	<u> </u>	-	\$ 50.00		-	
List Name of Installing Contractors	21. Services a. 0 through 1		-	\$ 20.00		-	
Heating Burkhandt	b. 101 throug		-	\$ 30.00			
Air Cond	c. 201 throug d. 400 throug			\$ 50.00		-	
Plumbing	e. Per 100 an			\$ 60.00		+	
Please Note:	22. Temporary permits, inclu			\$ 60.00		1	
The undersigned hereby submits a permit application for			+	\$ 60.00	 		
the electrical installation for light, heat or power as prescribed & agrees to comply with all applicable State,	24. MINIMUM FEE FOR AN	IY ONE PERMIT*	+	\$ 60.00		+	
Local Codes and Ordinances regulating the installation of electrical wiring & equipment in the Village of Brown	25. DOUBLE FEES for work started before obtaining permit			1		<u> </u>	
Deer.	MAKE CHECKS PAYABLE T	O VILLAGE OF BROWN DEER TOT	AL PEI	RMIT FEES	\$ 600	00	
*Where addt'l electrical permits on the same job are necessary, the minimum fee does not apply.					1.020	100	

Inspections are required before any work is concealed, when work is complete and prior to Occupancy or Use. Please Have Permit Number and Address When Requesting Inspections. Please Give At Least 24 Hours Notice. FINAL INSPECTIONS ARE MANDATORY.

Signature Of Applicant: Revised 1/24/14

(I acknowledge that I have read and understand the cautionary & statute statements)

Date:



Village of Brown Deer

4800 W. Green Brook Dr. Brown Deer, WI 53223 414-371-3030 / Fax 414-371-3045 (PLEASE TYPE OR PRINT WITH A BALL POINT PEN) PERMIT NO:

PH <u>18 - 0108</u>

Heating, Ventilation & Air Conditioning Permit Application

Project Address:	One & Two Family	□ c	ommercial		
Project Address: 3435 W	Pelican Un Brown	1000	r 53209	}	
Insta	ll (1) gas formace +	12/5		(
			Owner Telephone:		
Test +Oebbje Woccupant/Tenant	100192		414-44	2-850	\overline{O}
homem	. mer		Telephone:		
Contractor's Name		Contact Pe	erson: (Print Name)		
Mailing Address	eating	Om	rivea		
8232NT000+	mia Ave		Contractor: (Man	The state of the s	
City, State, Zip	53264	Telephon	SI Ebec	tric	Cold This beginning (
Heating Co. License No. & Expiration	on Telephone:	26	2-781-3	631	
520V 5-23-	22 1/2/ 2 = -	Contracto	r Number:		Estimated Cost of Jo
Make and Model of FURNACE:	BTU's	Mal O 10		136	\$ 986000
Unit #1 Bryant 980	770.0000		del of AIR CONDIT		Топладе
Unit #2	e11342080 89000	Unit #1	Dryant 18	6BIVACO	e 3700
EXEMPTION CONTRACTOR OF THE PROPERTY OF THE PR		Unit #2			Tonnage
NEW BUILDING, REPLACEM	SCHEDULE OF INSPERING AND MODIFICATIONS OF HEATI	CTION F	EES CONDITIONAL		
Gas, Oil, Or Alternative Fuel Fu	rnace and Boiler		Rate		
	One & Two Family -1st 150	,000 BTU	\$ 60.00	Count	Fee
	Commercial -1st 150		\$ 60.00		6000
	Each Addt'l 50,000 BTU Or Fraction		\$ 16.00		
Air Condition	Maximum	Per Unit	\$ 750.00		
Air Conditioning	One & Two Family -1st 150		\$ 60.00	Control of the	100GE
	Commercial –1st 150,		\$ 60.00		00
	Each Addt'l 50,000 BTU Or Fraction		\$ 16.00		
Fireplace & Wood Burning Stoves	Maximum	Per Unit	\$ 750.00		
Commercial/Industrial Exhaust Hoc	dc & Exhaust C		\$ 60.00		
leating & A/C Distribution Systems	(Dustruck) S55 445		\$ 155.00		
AIR CONDITIONED ((Ductwork) PER 100 S.F. OF AREA HEAT sq. ft. divided by 100 = "Count")	TED OR	\$ 1.80		
	Plan Ex	am Fee	\$ 60.00		
	Re-inspect	ion Fee	\$ 60.00		
B. III -	Failure to Call for Ins	pection	\$ 60.00		
Double Fees If Work Is	Started Before Permit Is Issued For First	Offense	\$ 120.00		
	Triple Fees For Subsequent (Offenses	\$ 180.00		
	MINIMU	M FEE	\$60.0	0	
** OIL TANK REMOVAL SHALL BE P	ERFORMED BY A QUALIFIED LICENSED CONTRACTOR		TOTAL DEDA		s 120°°
e applicant agrees to comply with all municipa the department, the municipality, agency, or or other penalty. Commercial or buildings has			CE FERM		

if the department, the municipality, agency, or inspector, and certifies that all of the above information is accurate. Failure to comply may result in suspension or revocation of this permit or other penalty. Commercial or buildings housing over two families shall have state approved heating plans with this application. Residential heating plans, heat loss calculations, and specifications of the equipment to be installed in new buildings shall be submitted with this application.

FINAL INSPECTIONS ARE MANDATORY. Please have permit number and address when requesting inspections. Give at least 24 hours notice.

Signature Of Applicant:





WELL OPERATION PERMIT

Brown Deer Water Utility

4800 West Green Brook Drive Brown Deer, WI 53223 357-0145 Permit #: 031

Date Issued: 6/30/99

This Permit authorizies the owner of the private well located at the address listed below to operate the well for a period of five (5) years from date of issue.

Owner's Name: FREDERICK & JUANITA MAI

Parcel ID #:

0651040

Street Address: 3435 W PELICAN LANE

City: BROWN DEER

APPROVED BY:

(Water Superintendent)



No: 3910

CERTIFICATE OF COMPLIANCE VILLAGE OF BROWN DEER, WISCONSIN

Date: April 9, 2001

Issued to:

Frederick and Juanita Mai

Address:

3435 W. Pelican Lane

This Certificate of Compliance permits a change in occupancy of the premises located at 3435 W. Pelican Lane, in Brown Deer, Wisconsin, any time within one year from date hereof, and indicates that so far as can reasonably be determined by a visual inspection of the premises and a review of the Village records, the premises meet the requirements of Chapter IX, Article 9 of the Brown Deer Administrative Code, Volume 1. Neither the Village of Brown Deer nor the Building Inspector assumes any liability in or as a result of the inspection or issuance of this Certificate of Compliance and by the issuance of this Certificate of Compliance does not guarantee or warrant as to the condition of the premises inspected.

Building Inspector, Village of Brown Deer



Village of Brown Deer

4800 West Green Brook Drive • Brown Deer, WI 53223-2496

Phone: (414) 371-3000

Ok to Issae 4-6-01

Fax: (414) 371-3045

February 14, 2001

Mr. & Mrs. Frederick Mai 3435 W. Pelican Lane Brown Deer, WI 53209

Re:

Certificate of Compliance Inspection

Dear Mr. & Mrs. Mai:

A recent inspection of your dwelling, located at **3435 W. Pelican Lane**, disclosed the following violations of the Brown Deer Code of Ordinances:

BROWN DEER BUILDING/ELECTRICAL PERMITS

Section 30.36-38/Section 1-1.11

H.V.A.C. and Electrical Permits are required for the installation of a furnace and central air conditioning. No permits were issued or authorized for the furnace and air conditioning that were installed in this dwelling. The necessary permits shall be obtained and the installation shall be inspected by the Brown Deer Electrical Inspector. Double Fees will be assessed due to the furnace and air conditioning being installed prior to the issuance of the proper permits.

NATIONAL FUEL GAS CODE

Section 5.3.3

The confined space enclosing the furnace shall be provided with (2) permanent openings located within 12" of the top and bottom of a wall communicating directly with an additional room of sufficient volume so that the combined volume of all spaces meets the requirement of an unconfined space which is an area greater than 50 cubic feet per 1000 BTU input. Each opening shall be provided with the minimum free area of one square inch per 1000 BTU of both appliances. The calculated free area of each opening shall be at least 142 sq. inches.

BROWN DEER BUILDING CODE

Section 30.15 (9) e

The exhaust fan in the main bathroom shall be properly ducted to the exterior of the building.


Section 30.36

The gas piping on the clothes dryer line shall be properly capped.

WISCONSIN STATE PLUMBING CODE

<u>COMM 82</u>

The trap at the kitchen sink is leaking and shall be repaired or replaced.



Mr. & Mrs. Frederick Mai February 14, 2001 Page two

COMM 82.32

The flexible trap on the wash basin in the half-bath is not permitted and shall be replaced with approved rigid material.

NATIONAL ELECTRICAL CODE

N.E.C. 384-13

Fine A/C breaker in the electrical panel box shall be properly identified and clearly labeled.

N.E.C. 440-21

The 45 amp breaker for the air conditioning disconnect is over-rated for this unit. The name plate on the equipment lists a maximum amperage of 30 for this unit. The wiring for the air conditioning equipment shall be reviewed by a licensed electrical contractor and corrected to meet the minimum standards of the National Electrical Code.

The violations noted herein shall be corrected on or before April 14, 2001. Please notify my office at 371-3030 when the corrections have been made so a reinspection can be conducted and the Certificate of Compliance issued.

Sincerely,

Robert G. Premo Building Inspector

RGP:ejb

CERTIFICATE OF COMPLIANCE INSPECTION REPORT

	ADDRESS: 3435 W. PELICAN LN.
	OWNER:
	INSPECTION DATE: Z-13-01 3Pm.
1	H.V.A.C. Built: 1954 DUNED. 25yes.
	H.Y.A.C.
	Furnace/Boiler - Proper InstallationNo
X	Comments:
/	V FOR PERMIT? BEESE. HE & A/C.
	Air Conditioning - Proper InstallationYesNo
1.4	Comments: 45 yes. Old
X	Comments: 45 yes. 260 V For Permit? Books Ht. 4AK
	Wall/Space Heater - Proper InstallationYesNo
	Comments: A.
	Fireplace - Proper Installation Yes No
	Comments: Marcueal Masoney Fineslace.
	Wood Burning Appliance - Proper InstallationYes No
	Comments:
	37,500.00
¥	Other-Proper Installation Yes No 110,000. Comments: THE GRICE RED 147,500 (2) 97 142 SQ. In. EACL 7,150 C.F.A.
	Comments: 147,500
8	Duct Exhaust Fra From Main Box to
To the second	Duct Exhaust In Ever main Bon to
	Exterior

	BUILDING
	Basement Remodeling - Proper InstallationYesNo
	Comments: Pastial PEC. Room. / Campay/Works/
	- Olth
	Screen/Patio Room - Proper InstallationYesNo
	Comments: 7.
	Misc. Remodeling - Proper Installation Yes No Comments: Family Room Amilian 1978.
	Garage - Proper Installation Yes No
	Comments: ATTACHEO. Z.C.
and a	Stairways - Proper InstallationYesNo
	Comments:
	Handrails - Proper Installation Yes No
	Comments:
	Guardrails - Proper InstallationYesNo
	Comments:
	Basement Bedroom(s)
	Comments:

Polystyrene Insulation Comments: Styp. Form Basement Walls

Daywoller. Other - Proper Installation _____Yes _____No Comments: FIRE CODE Smoke Detectors - Proper Installation Yes _____No Comments: V Fire Wall (Garage; breezeway) - Proper Installation Yes No Comments: Other - Proper Installation _____Yes _____No Comments: **PLUMBING** Basement Toilet Room - Proper Installation _____Yes _____No Comments: Water Heater _______(Gas) _____(Electric) - Proper Installation _______Yes ______No Comments: Bar Sink / Darkroom Sink- Proper Installation _____Yes _____No Comments: A

H

	Dishwasher - Proper Installation YesNo
	Comments: 405. Olora Boasonitaire Coop
	Fixtures Added - Proper Installation Yes No
	Comments: Washbasin.
	Damaged Fixtures Comments: LEMING FRAD. AT KIRCHSING
_	Other - Proper InstallationYesNo
-	Comments: Flex Jago, on Washbasin A.
,	BROWN DEER CODE Well System Working Abandoned Comments: Premitted by B.D. Watel
	Swimming Pool - Proper InstallationYesNo Comments:
-	Sump Pump - Yes No Comments: U.6. to Ortoh.
_	Address Numbers - ConformingYesNo
(Comments:

	Comments: No STORAGE PLAGE.
	ELECTRIC
	Garage Wiring - Proper Installation Yes No
	Comments:
	Garage Door Opener - Proper Installation
	Comments: 405.
	Basement Remodeling - Proper Installation Yes No
	Comments:
	Aid Continuing The Co
1	Air Conditioning/Heating Units - Proper Installation Yes No
4	Comments: A/C unit Breadest overnattale 45 Amp instead of 30 Amp.
	45 Amp instead of 30 Amp.
	Patio/Screen Room - Proper InstallationYesNo
	Comments: \sqrt{a} .
	Lamp Post/Exterior Lighting - Proper Installation Yes No Comments: Yes No
	Comments: Light Post Front. york.
	Elect Elect. Dryer/Range - Proper Installation Yes No
	Cap. Cas pipino on Dryer Line

	Comments:
	Swimming Pool Wiring - Proper InstallationYesNo Comments:
	Other - Proper InstallationYesNo Comments:
	Additional Comments and/or Explainations:
7	LABEL A/C. BETALLOR

VILLAGE OF BROWN DEER 4800 W. Green Brook Drive Brown Deer, WI 53223 Phone (414) 371-3030

UNIFORM HEATING, VENTILATING & AIR CONDITIONING PERMIT APPLICATION

OFFIC	E USE ONLY
Permit No.	2684

Phone (414) 371-3030 FAX (414) 371-3045 PERMIT APPLICATION			Received			
ISSITING						
MUNICIPALITY TOWN OF	TY VILLAGE PROJECT LO	CATION				
	PROJECT DE	SCRIPTION				
OF		NE & TWO FAMILY	MULTI-FAMILY		COMMERCIAL	
OWNER'S NAMES and may	34 35	AILING ADDRESS	lon	TELEPHONE (Incl.	ude Area Code)	
CONTRACTOR'S NAME	7/ >	· in incini	ELECTRICAL CONTRA		7700	
Janis Deere	Healing		Consal	datud	Elect.	
MAILING ADDRESS 5665 N 27	A m	53209	TELEPHONE (Include	Area Code)		
and only	STATE	53204 ·	ELECTRICAL LICENSE	NUMBER		
HEATING LICENSE NUMBER	410	TELEPHONE (Include Area Code	COMPLETION DATE		TED COST OF JOB	
MAKE & MODEL OF FURNACE	BTUs	MAKE & MODEL OF A	10	\$ 3,	000	
~		MARC & MODEL OF A	,		TONNAGE	
UNIT #1 Jeorgne	(00,00).				Skey	
UNIT #2 Ruyne AC	36,000.		,			
** C.F.C. HANDLING SHALL BE PERFORMED IN ** OIL TANK REMOVAL SHALL BE PERFORMED ** PROPER ASBESTOS ABATEMENT SHALL BE	IN ACCORDANCE WITH ILLIE 10		7			
		F INSPECTION FEE				
NEW BUILDING, REPLACEMEN	IT AND MODIFICATIONS OF HEA			MISCELLANEC	HIS ITEMS	
			RATE	COUNT	FEE	
GAS, OIL OR ALTERNATIVE FUEL FURNACE AN	ID BOILER: ONE & TWO FAMILY - 1st	150.000 BTU	\$ 30.00	1	\$ 30.00	
		150,000 BTU	30.00	1	\$ 30-00	
		OR FRACTION THEREOF	10.00			
	,	MAXIMUM	750.00			
AIR CONDITIONING	ONE & TWO FAMILY - 1st	3 TONS	30.00	1	30.00	
(Include location sketch on back of white copy)	COMMERCIAL - 1st	3 TONS	30.00		30.00	
	EACH ADDT'L. TON OR FF	RACTION THEREOF	10.00			
		MAXIMUM	750.00			
FIREPLACE AND WOOD BURNING STOVE	: ·:: · · :::: · · : · · · · · · · · ·	, 	30.00			
COMMERCIAL / INDUSTRIAL EXHAUST HOODS	AND EXHAUST SYSTEMS		30.00			
HEATING AND A/C DISTRIBUTION SYSTEMS (DUC	TWORK) - PER 100 SQUARE FEET OF AI	REA HEATED/AIR CONDITIONED.				
THIS DISTRIBUTION SYSTEM SERVES	SQUARE FEET (\$2	25.00 Minimum)	1.00			
PLAN EXAM FEE			30.00			
MINIMUM PERMIT FEE			30.00			
REINSPECTION FEE			30.00			
FAILURE TO CALL FOR INSPECTION		. A	10.00			
DOUBLE FEES WILL BE CHARGED IF WORK IS	STARTED BEFORE PERMIT IS ISSUED	o aa			60.00	
					\$ 100	
THE APPLICANT AGREES TO COMPLY WITH A	ALL MUNICIPAL ORDINANCES AND W	ITH THE CONDITIONS OF THIS F	TOTAL PER		NOE OF THE BERNIT	
CREATES NO LEGAL LIABILITY, EXPRESS OR ACCURATE. FAILURE TO COMPLY MAY RESULT SHALL HAVE STATE APPROVED HEATING PLATO BE INSTALLED IN NEW BUILDINGS SHALL B REQUESTING INSPECTIONS. GIVE AT LEAST 2	T IN SUSPENSION OR REVOCATION OF ANS WITH THIS APPLICATION. RESIDE IE SUBMITTED WITH THIS APPLICATION	THIS PERMIT OR OTHER PENALT	Y. COMMERCIAL AND BU	HAT ALL THE ABO ILDINGS HOUSING	OVE INFORMATION IS OVER TWO FAMILIES	
SIGNATURE OF APPLICANT	Janis O.S.	lear	date 3	-23-	2001	
	DO NOT FILL IN BELO	W - DEPARTMENT U	ISE ONLY			
			MIT ISSUED BY MI	JNICIPAL AGI	NT	
INSPECTION \$	PUIL DING BERNIT "					
PLAN EXAM	BUILDING PERMIT #					
PRELIMINARY FEE	STATE APPROVED YES	NO DATE				
BALANCE DUE	DATE ADDROVED					

VILLAGE OF BROWN DEER

4800 W. Green Brook Dr. Brown Deer, WI 53223 414-371-3030 • FAX 414-371-3045

APPLICATION FOR ELECTRICAL PERMIT

PLEASE TYPE OR PRINT WITH BALL POINT PEN

Date 3-27-0/

License No. -

OFFICE USE ONLY
Permit No. 12619
Received
Service
Rough-in
Final

Builder		EREd Mai	Occupant	/Tenant				
3435 W. Pelica	n_	Owner Telephone			Tenant Telephone			
ESTIMATED COST OF JOB \$ 150 Buildings A Residential	No	. Description	Qty.	Rate of Fees	Dollars	Cent		
Commercial	1	Outlet for switches, receptacles & devices			.40			
□ Industrial □ New Construction	2	Incandescent lighting fixtures - per lamp			.40		+	
☐ Additional Rooms	3	Fluorescent lighting fixtures - per lamp			.40		+	
□ Remodeling	4	HID lighting, etc per lamp			2.00		_	
□ New Occupancy	5	30 amp outlets & larger outlets (ranges, ovens,	dryers)		5.00		 	
Where on premises?	6	Garbage disposal	7 - 7		5.00		+	
Describe New Furnace and Central Air	7	Dishwasher			5.00		-	
and Central Hip	8	Water heater			5.00		\vdash	
	9	Motors (per h.p. or fraction thereof)			.50		-	
List Name of Installing Contractor	10	Transformers, generators, rectifiers (per KW and U.P.S.	systems)		.50		+-	
HEATING BEESE HEATING	11	Automatic heating equipment (furnaces, boile		,	5.00		+	
AIR CONDITIONING	12	Electric heating equipment (per KW)			.50	5	60	
PLUMBING	13	Air conditioner, refrigeration units and compres	sor	,	5.00	5	00	
Please Note:	14	Dimmer and timing devices	001		2.00		100	
Brown Deer has an exterior Security	15	Feeder or subfeeder			3.00		+	
Lighting Ordinance (84-19). A separate,	16	Solar-photovoltaic systems			25.00		-	
approved authorization form must be	17	Wireways, busways, underfloor raceways, aux. gut	tors/ft		.30			
attached to this application covering	18	Strip & track lighting, plug-in strip & similar sys./f			,30			
all exterior Security Lighting.	19	Signs, illuminated	1.		25.00		-	
REMARKS:	20	Swimming pools, jacuzzis, spas or hot tubs			 			
REMARKS.	21	Services			30.00			
	-	a. 0 through 175 amps			10.00			
		b. 200 through 350 amps			10.00		-	
	-	c. 400 amps and above			15.00		ļ	
	22				25.00			
	-	Temporary permits, including services, 90 days			20.00			
	23	Reinspections	_		20.00		ļ	
	24	FAILURE TO CALL FOR FINAL INSPECTION	-		20.00			
	25	MINIMUM FEE FOR ANY ONE PERMIT *			30.00		<u> </u>	
	26	DOUBLE FEES for work started before obtaining o					ļ	
	mini	ere additional electrical permits on the same job are no mum fee does not apply.	ecessary, th	10	TOTAL FEES	300	00	
heat or power as prescribed and a	agree	tion for a permit for the electrical installations to comply with all applicable State and Lenstallation of electrical wiring and equipment	ocal		MAKE CHECI VILLAGE OF MAIL TO: Elec	BROWN D	EER	
Control			7/ 1		//			
Contractor		Cupon vising Electrician (C	Harry dest	11		-		

Mr. and Mrs. Frederick P. Mai 3435 W. Pelican Lane Brown Deer, Wisconsin 53209

065-1040

Dear Mr. and Mrs. Mai:

x Family Room Addition

1977

\$5,500

\$16,900 (Partial) \$22,400



No: 4888

Date: January 30, 2006

Issued to:

Chris and Linda Buetow

Address:

3435 W. Pelican Lane

This Certificate of Compliance permits a change in occupancy of the premises located at **3435 W. Pelican Lane**, in Brown Deer, Wisconsin, any time within one year from date hereof, and indicates that so far as can reasonably be determined by a visual inspection of the premises and a review of the Village records, the premises meet the requirements of Chapter IX, Article 9 of the Brown Deer Administrative Code, Volume 1. Neither the Village of Brown Deer nor the Building Inspector assumes any liability in or as a result of the inspection or issuance of this Certificate of Compliance and by the issuance of this Certificate of Compliance does not guarantee or warrant as to the condition of the premises inspected.

Building Inspector, Village of Brown Deer



COMMUNITY SERVICES DEPARTMENT
INSPECTION DIVISION
4800 West Green Brook Drive
Brown Deer, Wisconsin 53223

July 8, 2005

Mr. & Mrs. Chris Buetow 3435 W. Pelican Lane Brown Deer, WI 53209 OK TO ISSUE IF WELL SYSTEM IS IN COMPLIANCE 9-8-05. PH.

Re: Certificate of Compliance Inspection

Dear Mr. & Mrs. Barton:

A recent inspection of your dwelling, located at **3435 W. Pelican Lane**, disclosed the following violations of the Brown Deer Code of Ordinances:

PROTECTIVE SERVICES CODE

Section 12-14.06 (B) (13)

All one and two family dwellings in the Village of Brown Deer shall have not less than one approved carbon monoxide detector installed in each residential unit if the dwelling contains a fossil fuel powered appliance which is within the interior of the building structure. The detector shall be installed within 20 feet outside the area of all sleeping rooms and in accordance with the manufacturer's specifications for installation. A carbon monoxide detector is required on the first and second floors of this dwelling.

BROWN DEER PLUMBING CODE

Section 1-1.03

OK

A Plumbing Permit is required before any plumbing work commences. No permit was issued or authorized for the installation of the kitchen sink and dishwasher in this dwelling. The Plumbing Permit shall be obtained and double fees will be assessed due to the installation commencing prior to obtaining the necessary permit.

WISCONSIN STATE PLUMBING CODE

<u>COMM 82.40 (8) (f)</u>

A mechanical water hammer arrestor is required at the dishwasher. The old trap must be properly abandoned and capped.

NATIONAL ELECTRICAL CODE

The following electrical code violations shall be reviewed by a licensed electrical contractor and corrected to meet the minimum standards of the National Electrical Code.

A cable clamp is required for the B-X wiring connection at the garbage disposal.

The receptacle at the entry door must be replaced with a G.F.C.I. type and properly secured.

The fixtures wired with extension cords in the basement and garage must be removed. The reverse polarity outlet at the kitchen counter must be replaced with a G.F.C.I. type.

OK

Mr. & Mrs. Chris Barton July 8, 2005 Page two

BROWN DEER CODE

Section 11-1.36

The existing well system on this property must be in compliance with Ordinance #96-15 which regulates the abandonment of unused wells and the issuance of a well operation permit for those property owners who wish to continue the use of their private wells. You may contact the Brown Deer Water Utility at 371-3080 for an informational packet regarding these requirements.

The violations noted herein shall be corrected on or before September 8, 2005. Please notify my office at 414/371-3030 when the corrections have been made so a reinspection can be conducted and the Certificate of Compliance issued.

Sincerely,

Richard P. Hensch Building Inspector

W Heuse

RPH:ejb

CERTIFICATE OF COMPLIANCE INSPECTION REPORT

ADDRESS: 3435	W. PELICA	W		
OWNER: CINOSA &	CHRIS i	3 UETOU	ر	
INSPECTION DATE:	7-6-05	TIMI	E: 9:30	
H.V.A.C.		OWNE	D 49R	BUIL
Furnace Boiler	☐ Gas ☐ Forced Air☐ Oil ☐ Hydronic	Age:	+478	35.
✓ No Violations Observed ☐ Violations:				
	1			
Air Conditioning: Yes No Violations Observed			+ 4 7%	> 2
□ Violations:				
Wall/Space Heater: ☐ Yes No Violations Observed ☐ Violations:				
Fireplace: Ves				
✓ No Violations Observed □ Violations:	#2 □ Masonry			
Wood Burning Appliances:	□ Yes 🗷 🗖 No	□Stove	□ Incinerator	
No Violations Observed				
□ Violations:				


y = x ±	Exhaust Kitchen Bathroom No Violations Observed Violations:
	Combustion Air Issues No Violations Observed Violations:
	Other Issues:
	BUILDING Basement Remodeling Wes No WAge OVER 47ES Type: MULTIPUR ROOMS. No Violations Observed Violations:
	Basement Bedroom
	Screen/Patio Room
4	Stairways/Steps

Handrails Yes No No Violations Observed	Guardrails	□ Yes	□No
□ Violations:			
Rigid Foam Insulation	E No		
No Violation Observed			
☐ Violation:			
Other Issues:			
FIRE CODE			
Smoke Detectors (1 required each level)	Basement	P Yes	□No
	1 st Floor		□No
No Violations Observed	2 nd Floor	Yes	□No
□ Violation:			
_ violation,			
C.O. Detector Within 20' of Bedrooms	□ Yes	E No	
✓ □ No Violations Observed			
Violation: CO. DRTRCFOR	PRQUI	RED -	157 4 2ND
21/2 CAR ATTACHED.			
Garage: Firewall ZYes No	Fire l	Door Z	es □No
□ No Violations Observed □ Violation:			
□ Violation:			

PLUMBING

	Basement Toilet Room □Yes ☑No Shower □Yes ☑No □ No Violations Observed □ Violation:
	Water Heater ☐ Gas ☐ Electric Approximate Age: OLDRR. No Violations Observed ☐ Violation:
	Bar Sink/Darkroom Sink - □ Yes ☑ No Violations Observed □ Violation:
	Dishwasher - Yes INO Approximate Age: NEWER I No Violations Observed Violation: MECH SHOCK ARRESTOR REQUIRED, OLD TRAIT TO BE PROPERLY CAPPED AND ABANDONED,
	Fixtures Added/Replaced Wes No What? No Violations Observed Violation:
/	Damaged Fixtures □Yes ☑No What?□ Violation:
	Other Issues:

BROWN DEER CODE



* * * * * * * * * * * * * * * * * * *	ELECTRIC	2				
	Appliances	Range	□ Yes □ No	□ Ga	as del ectric	
		□ Dryer	□ Yes □ No	□ Ga	as D Electric	
		□Dishwash	er 🗷 Yes 🗆 No			
	/	□ Disposal	ZYes □No	NOT	WORKING.	
0.4	□ No Violati	ons Observed			·	
	Violation:	PROPER	CONUR	STOR	REQUIRED	15
		Finished ions Observed	□ Unfinished			
	□ Violation:					
	□ No Violati	ng Kyes ions Observed RECEPT D TO		T RIUT	RY DOOR TO ND PROPERLY	BE SECURE
	No Violati	ons Observed	⊠Yes □ No			
		ons Observed				·
	Lamp Post					

a 64 g	Patio/Screen Room							
	Damaged Fixtures DYes INO DRemove IReplace Violation: FIXTURES WIRED WITH EXTENSION CORDS IN BASEMENT AND GARAGE TO BE REMOVED.							
	IN BASEMENT AND CARAGE TO BE REMOVED. Swimming Pool Wiring Served No Violations Observed Violation:							
	Electrical Service Panel Directory Ves No No Violations Observed UViolation:							
	Other Issues:							
	Additional Comments and/or Explanations: REV PORATITY OUTLES AT KITCHEN COUNTY TO BE REPLACED WITH GRET							

VILLAGE OF BROWN DEER

4800 W. Green Brook Drive Brown Deer, WI 53223 Phone (414) 371-3030 FAX (414) 371-3045

SIGNATURE OF PLUMBER

PLUMBING PERMIT APPLICATION

Permit No. 10254

]						
PROJECT LOCATION:	3435	W.	Pelican	In	- Brown D	eer	W	
PROJECT DESCRIPTION:	1075hu	JARN	er req	Dlacen	rent			
1 & 2 FAMILYM	ULTI-FAMILY	co	MMERCIAL			\$	TIMATED CO	OST OF JOB
O WILLER O HARIE	stopher	- Du	LING ADDRESS	3435	w. Pelican L	u. TH	ELEPHONE (I	nclude Area Code)
SCHIAM	4/WV	n bi	nq			41	19-4	66-26.66
PLUMBING CONTRACTOR	100		\cup	1.	/wxukee W	TE		nclude Area Code)
4-9820	WS	401	idan	Ma	/WAUKee W	'~ S	352	25
MAILING ADDRESS			CITY		STATE	ZIP	11 .11	. 14
<u> </u>							1 58	590
BONDING INSURANCE CO.			MASTER PLI	UMBER'S NAM	Æ.	MASTE	R PLUMBER	CREDENTIAL#
		-	CHEDULE O	F INCDEC	FION FEEC			
NEW PLUMBI	NG. REPLAC	EMENT	AND MODIFIC	ATIONS O	FEQUIPMENT AND MIS	THE LANGE		#D
				THOMS O	F EQUIT MENT AND MIS	CELLANE	JUS II EN	15
	COUNT	EACH	FEE			COUNT	EACH	FEE
Automatic Washer Backflow Preventor		6.00		26.	Sanitary Building Drain			122
Backflow Preventor Bath Tub		6.00 6.00			First 100 Feet Over 100 Feet		30.00	
4. Dishwasher		6.00	6,00	2.7	Storm Building Drain		.35/ft.	
5. Drinking Fountain		6.00			First 100 Feet		30.00	
Ejectors or Pump Floor Drain		6.00		••	Over 100 Feet		.35/ft.	
8. Garbage Grinder		6.00 6.00		28. 29.	Manhole Catch Basin		10.00	
9. Grease Trap		6.00			Water Service		10.00	
10. Hose Bibb		6.00			First 100 Ft. Lateral		30.00	
11. Laundry Tray 12. Lavatory		6.00 6.00		21	Over 100 Ft. Lateral		.35/ft.	
13. Shower		6.00		31.	Sanitary Building Sewer First 100 Ft. Lateral		20.00	 -
14. Sink		6.00	4.00		Over 100 Ft. Lateral		30.00 .35/ft.	·
15. Site Drain 16. Slop Sink		6.00		32.	Storm Building Sewer		133716.	
17. Storm Sewer Conductor		6.00 6.00			First 100 Ft. Lateral		30.00	
18. Sump Pump		6.00	=====	33.	Over 100 Ft. Lateral Roughing in of Fixtures		.35/ft 5.00	
19. Urinal		6.00		34.	Residential Fire Sprinkler Syste	ms	30.00	
20. Wash Fountain 21. Water Closet		6.00 6.00		35.	Other Fixtures	#	6.00	
22. Water Heater		0.00				1		
Gas		6.00						
Electric 23. Water Softener		6.00						
24. Water Treatment Device		6.00 6.00			MINIMUM PERMIT FEE REINSPECTION FEE		50.00	50
25. Whirlpool		10.00			FAILURE TO CALL FOR INST	PECTION	50.00 50.00	511.00
							20.00	
								-)
					TOTAL PE	RMIT FEE	: \$_ //	1/).00
	DOUBLE I	TEES ADE	DHE IE WORK I	CCTABTED	BEFORE PERMIT IS ISSUEI	_	70	
Revised Jan, 2004	DOUBLE I	LES ARE	DUE IF WORK I	SSIARIED	BEFORE PERMIT IS ISSUEI	,		
THE ADDITION OF THE PARTY OF TH				-3:		<u></u>		
THE APPLICANT AGREES TO CO THE PERMIT CREATES NO LEGA ABOVE INFORMATION IS ACCURATE.	IL LIABILLI Y, EXI	PRESS OR I	MPLIED OF THE DE	PARTMENT N	AT INTOTE AT ITV ACENOV OF INTO	DECTOD AND	CERTIFICA	TELLOT AND OTTO
ABOVE IN ORMATION IS ACCUM	KAIE, PAILUKE	LO COMPL	Y MAY RESULTIN S	HISPENISION O	ID DEVICE ATION OF THE BEDLAS	מ מידודיים מה יו	TATAL COLUMN	1 10 400 Pa 1 Ca
ACCORDANCE WITH COMM. 82.	20 OF THE STATE	OF WISCO	ALLED IN A NEW O	R REMODELE	D BUILDING SHALL BE SUBMITT	TIN WITTITIO	C ADDITIONS	COLUMN
AND ADDRESS WHEN REQUES	TING INSPECT	SIS. PLEA	SE GIVE AT LEAST	r 24 HOURS N	OTICE.	x. PLEASE F	IAVE PERM	IT NUMBER
	,	,	/ /					





Brown Deer Water Utility

4800 West Green Brook Drive Brown Deer, WI 53223 371-3080 Permit #:

059

Date Issued:

1/30/06

This Permit authorizies the owner of the private well located at the address listed below to operate the well for a period of five (5) years from date of issue.

Owner's Name: Chris Buetow

Parcel ID #:

'0651040

Street Address: 3435 W. Pelican Lane

City: Brown Deer



(Water Superintendent)







Co., Inc. 9820 West Sheridan Avenue, Milwaukee, Wisconsin 53225 • P/414-466-2666 • F/414-466-2676

January 23, 2006

Mr. Chris Buetow 3435 W. Pelican Lane Brown Deer, Wisconsin 53209

Dear Chris:

Today I inspected the well system at the above mentioned property. The well casing does extend the proper distance above grade. The pressure tank, controls, wiring and pressure gauge are in good working order. Our system running test revealed that the pump delivers adequate flow. The state water sampling faucet is installed at the proper height.

A water sample was taken to Milwaukee Milk Producers for testing and the results of this test are on a separate sheet.

This inspection includes information, lists facts and conditions for the visible portions of the well system at the time and date of this inspection. This report does not imply or warrant the expected life or below grade condition of this system. If you have any questions or concerns please feel free to call us.

Todd L. Schram

		Water Testi	ng Form	For W	later Sys	tems			
Collection D	ate (MM-DD-YY)	Time	lm	Collected By	7	License # (if pum	p installer/well driller)		
JANUA Owners Nam	4eJ 23,200	6 10:00	m	101	D				
CHRI		,							
Owners Stre	5 W. PECICI	an / anie		Sampling Address (Street or Legal Discription)					
Ully, Salate, 2	Th Code			Town or City	9mE				
DICO	Name VEFR	WI. 532	09	<u> </u>					
Mail Results	Schram Bay	yshore Plumbir	ng Co., Ind	3		Send Copy of n	esults to DNR?		
То:	9820 West	Sheridan Aver	nue		•	Yes	No		
	Milwaukee,	_	tata		Zip .	Phone: 414-46			
Approximate	Well Const. Date	Wis. Unique Well #		1			466-2676		
						ratory Use O	nly		
	Sampling Information				Minimal Med	is (Check One)	46		
Reason F			(4		OMPG =	Presence -	77		
4	Annual Test	Previous Unsafe	•		MUG =	Positive Positive	Negative		
	New Well	Pump Work		Bacteriok	ogical Resu	its / Interpret	-		
	Taste or Odor	Real Estate		SAFE (Coliform Absent)					
	Other Reasons:			UNSAFE (Coliform Present, Ecoli Absent)					
Sample Lo	ocation			UNSAFE (Coliform Present, Ecoli Present)					
	Bathroom Tap	Pressure Tank T	ap	Invalid-Please Submit Another Sample.					
	Kitchen Tap	Milkhouse				l Contamir			
	Other:			(These a	re optional and	they require add	fitional containors)		
Does the well	serve the public?	Yes No		(These are optional and they require additional contains Results SDWA N					
Public I.D. #				Nitrate		mg/l as N	10 mg/l as N		
	Well Construc	tion Information		Nitrite		mg/l as N	1 mg/l as N		
	Dritted	Driven Point		Fluoride		mg/l as Fl	4 mg/t as F)		
	Jetted	Dug	2	Lead		ug/i as Pb	15 ug/l as Pb		
	Other:			Copper		mg/l as Cu	1.3 mg/l as Cu		
Remarks:	2			Sodium		mg/l as Na	20 mg/l as Na		
				**Not	e ** The Sy	mbol < means	s "less than"		
			Your result	is considered S	late for Drinking	and Infant Formula			
			-	preparat	ion when your	result is less than	the SDWA MCL		
Water Q	uality Testing	Services [Date 1 23 06	Time		Lab Sample No.		
a division	of Milwaukee Mi	lk Producers			12:25 Analyst : Bacte	riological Incline	375		
Milwauke	Quality Contro	Laboratory		11-7-71	- myot. Daule	MANUFACTURE TO SERVICE	vert began		
2965 N R	rookfield Road	1-50		11/28	06 12	:500	275		
	d, WI 53045	□ Lab Cert □ WDATCP 108	17	Date / Time /	Analyst : Bacte	riological Result	Neponed		
	786-3120	WDNR 268		1/24	100	2:45	**************************************		

INSPECTION REQUEST

Contractor:		DateCalled In: 9-12-06
Contractor Phone:	Pager/Cell Phone	Requested Inspection Date:
Customer: Tom Wilson		Customer Phone: 357-8232
Job Address: 3435ω .	Pelican La.	Work Phone:
BUILDING	ELECTRICAL	PLUMBING
Permit #	Permit #	Permit #
1. Footing	1. Service	1. Waste & Vents
2. Foundation	2. Rough	2. Water
3. Rough Carpentry	3. Heating - A/C	3. Rough
4. Basement Slab	4. Fixtures	4. Inside Sewer
5. Insulation	Final/Occupancy	5. Storm Sewer
Final/Occupancy		6. Outside Sewer
Main Floor bath		Final/Occupancy
Date of Inspection: 9-12-06 Comments: Call to School	Date of Inspection: 9-12-06	Date of Inspection: 9-12-06
2		



No: 5328

CERTIFICATE OF COMPLIANCE

Date: June 8, 2009

Issued to:

Tomm & Laurie Wilson

Address:

2174 Fairway Circle

Canton, MI 48188

This Certificate of Compliance permits a change in occupancy of the premises located at **3435 W. Pelican Lane**, in Brown Deer, Wisconsin, any time within one year from date hereof, and indicates that so far as can reasonably be determined by a visual inspection of the premises and a review of the Village records, the premises meet the requirements of Chapter IX, Article 9 of the Brown Deer Administrative Code, Volume 1. Neither the Village of Brown Deer nor the Building Inspector assumes any liability in or as a result of the inspection or issuance of this Certificate of Compliance and by the issuance of this Certificate of Compliance does not guarantee or warrant as to the condition of the premises inspected.

Building Inspector, Village of Brown Deer

pm

E395- FCE. JGP

COMPLIANCE APPLICATION

VILLAGE OF BROWN DEER

FEE TO ACCOMPANY APPLICATION

4800 West Green Brook Drive Brown Deer, Wisconsin 371-3030 (FAX) 371-3045 Make Check Psyable To:
VILLAGE OF BROWN DEER

OFFICE USE ONLY

	37. 3000 (1121/0710		INSPECTION	DATE & TIME	
ADDRESS 3435 W. Pe	lican Ln		Thurs 1	Man 28 CHECK/CASH	5
TYPE OF OCCUPANCY: X S		WO-FAMILY	\$150.00	7	
CURRENT OWNER: Tom	+ Laurie WI	ison			
	+ Fairway Circle		STATE	48188	
		CILI	SIAID	ZAF	
TELEPHONE: (414	-) 364-6017				
AGENT FOR OWNER:		TELEPHON	VE: ()		
ADDRESS:					
NO.	STREET	CTTY	STATE	ZJP	
A CERTIFICATE OF COMPLIANCE WILL NOT CANNOT BE DEFUNDED.	HE ISSUED UNLESS REPAIRS ORDERED	BY THE BUILDING INSP	ECTOR ARE PERFO	rmed. Fee	

CH Nancy Bennaton 414-429-0816 (H) 414-964-0816

SIGNATURE OF APPLICANT

Buyer: Randy Harris

VILLAGE OF BROWN DEER

4800 W. Green Brook Drive Brown Deer, WI 53223 (414) 371-3030 FAX (414) 371-3045

APPLICATION FOR BUILDING PERMIT

6-2-09


DATE: April 17 20 06 PERMIT NO. 17579.
The undersigned hereby applies for a permit to remode Earthcome according to the following statement:
1. Owner: Tomm Wilson Telephone: 357-8232
2. Owner Address: 3435 W. Pelican City: Brown Deer Zip: 53209
3. Location of Structure: SAME
4. Cost of Job: 8,000 Fee: 180 Lot Block Subd.
5. Kind of Building (factory, office, store, dwelling): Home, Single Family
6. Class of Construction: To Be Occupied By: John Wilson
7. Name of Contractor: By Dune
7. Name of Contractor: By Owner Telephone:
9. ArchDesign Eng.: By Dune Telephone:
10. ArchDesign Eng. Address: City: Zip:
11. Is Building:OldNew
12. State in detail kind of occupancy or work to be performed: (Mention alterations, replacements, etc.)
Add second floor full bathroom
Convert first floor 1/2 bathrooms into
1 full bathroom
t is Hereby Agreed between the undersigned as owner or his/her agent, and the Village of Brown Deer, that for and in consideration of the premises and of the permit to construct erect, alter or install and the occupancy of building as above described, to be issued and granted by the Building Inspector, that the work thereon will be one in accordance with the descriptions herein set forth in this statement, and as more fully described in the specifications and plane becausith filed, and it is forther


It is Hereby Agreed between the undersigned as owner or nis/her agent, and the Village of Brown Deer, that for and in consideration of the premises and of the permit to construct erect, alter or install and the occupancy of building as above described, to be issued and granted by the Building Inspector, that the work thereon will be done in accordance with the descriptions herein set forth in this statement, and as more fully described in the specifications and plans herewith filed; and it is further agreed to construct, erect, alter or install and occupy in strict compliance with the ordinances of the Village of Brown Deer, and to obey any and all lawful orders of the Building Inspector of the Village of Brown Deer, and all State Laws relating to the construction, alteration, repairs, removal and safety of buildings and other structures and permanent building equipment.

Signed: 1

Contractor Certification Number:

HomeownEl






Tomm + Laurie Wilson 3435 W. Pelican Ln Brown Deer, WI 53209 414-357-8232 OPSTAIRS of HOUSE

ADDITION OF BIEM BATTLEOOM

and Floor.



VILLAGE OF BROWN DEER.

4800 W. Green Brook Dr. Brown Deer, WI 53223

414-371-3030 • FAX 414-371-3045 APPLICATION FOR ELECTRICAL PERMIT

Date 417 06
License No. Homeours

PLEASE TYPE OR PRINT WITH BALL POINT PEN

OFFICE USE ONLY

Permit No. 14827

Received

Service

Rough-in 5-30-06 RH.

Date

Builder					1 111011 4	0-209).F
		John Wilson	Occupan				
3435 W. Pelican	1	Owner Telephone	Occupan	A Y	Telephone		
3133 W. Pelican	7	357-8232	1	bar			
M. A. 20	No.	Description		Qty.	1	Dollars	Cents
ESTIMATED COST OF JOB \$ #10000	1 Outlet	for switches, receptacles & devices		1.	-		de
Bulldings 💆 Residential Commercial		descent lighting fixtures - per lamp		25	.50	3.	-
□ Industrial	3 Fluores	cent lighting fixtures - per lamp	<i>[</i>	2	.50	3.	0-0
☐ New Construction					.50		
Additional Rooms	5 20 202	hting, etc per fixture			6.00		
☐ Remodeling	5 30 amp	o outlets & larger outlets (ranges, ovens, c	dryers)		6.00		
☐ New Occupancy		ge disposal			6.00		
Where on premises?	7 Dishwa	sher			6.00		
Describe 1st Floor Bath	8 Water h	neater			6.00		
2" Floor Bath	9 Motors	(per h.p. or fraction thereof)	LI	m.	.70	2:	10
		ners, generators, rectifiers (per KW and U.P.S. sy	stems)	,,,,,	.70		10
List Name of Installing Contractor	11 Automo	atic heating equipment (furnaces, boilers)		7.50		
HEATING	12 Electric	heating equipment (per unit)	/				
		ditioner, refrigeration units and compresso	-		4.00		
AIR CONDITIONING	14 Dimmer	and timing devices, G.F.C.I. devices)	2	10.00		
PLUMBING				3	4.00	12:	00-
Please Note:		or subfeeder - sub-panel			15.00		
Brown Deer has an exterior Security	16 Wireway	rs, busways, underfloor raceways, aux. gutte	rs/ft.		.50	1	
Ughting Ordinance (84-19). A separate,	17 Strip & tr	rack lighting, plug-in strip & similar sys./ft.			.50		
approved authorization form must be		uminated			30.00		
attached to this application covering		assage bathtub - residential			10.00		
all exterior Security Lighting.	20 Swimmir	ng pools, jacuzzis, spas or hot tubs			50.00		
SCOPE OF WORK:	21 Services	a. 0 through 100 amps			20.00		
To the total of th		b. 101 through 200 amps			30.00		
		c. 201 through 400 amps		\rightarrow	50.00		
		d. 401 through 600 amps					
		e. Per 100 amps over 600			60.00		
	22 Temporo	ary permits, including services, 90 days			10.00		
	23 Reinspec				50.00		
					50.00		
		O CALL FOR FINAL INSPECTION			50.00		
		I FEE FOR ANY ONE PERMIT *			50.00		
	126 DOUBLE F	EES for work started before obtaining per	mit	ŀ			
	*Where additio minimum fee d	nal electrical permits on the same job are nece oes not apply.	essary, the		TOTAL FEES	50'	00
Liver of bower as prescribed that the	DIERS IO COM	a permit for the electrical installation ply with all applicable State and Loc n of electrical wiring and equipment	1		MAKE CHECKS VILLAGE OF E MAIL TO: Elect	BROWN DEE	R

Supervising Electrician (Signature)

Telephone

Zip Code 53209

State)

VILLAGE OF BROWN DEER

4800 W. Green Brook Drive Brown Deer, WI 53223 Phone (414) 371-3030 FAX (414) 371-3045

PLUMBING PERMIT APPLICATION

Permit No. 10431

	· · · · · · · · · · · · · · · · · · ·							
	4 3 5 W.		an Lan	9				
PROJECT DESCRIPTION:	residen	.ce						
XI & 2 FAMILYMI	JLTI-FAMILY	cc	OMMERCIAL				STIMATED CO	
OWNER'S NAME		MA	ILING ADDRE	e e				
	n Wildo							nclude Area Code)
Tomm & Lauri	3 WIISO	11, 34	55 W. J	Pelican L	ane	(414	/	57-8232
	D I l		00 37 () [L] Q L	M 1 52225	T	ELEPHONE (L	clude Area Code)
	STUMBIN	9, 58		sotn St.	Milwaukee 53225	466-	-6767	(414)
MAILING ADDRESS			CITY		STATE	ZIP		
Cincinnati I	nsuranc	е	Dale F	Malliburt	on	5.	195	
BONDING INSURANCE CO.			MAST	ER PLUMBER'S NAM	ME	MAST	ER PLUMBER	CREDENTIAL#
ATERES FOR SIR SPACE		S	CHEDUL	E OF INSPEC	TION FEES			
NEW PLUMBIN	G, KEPLAC	LEMENT	AND MOD	IFICATIONS O	F EQUIPMENT AND MIS	CELLANE	OUS ITEM	S
	COUNT	EACH	FEE			COLDIN	TI L CTY	
1. Automatic Washer	000111	6.00		26	Sanitary Building Drain	COUNT	EACH	FEE
2. Backflow Preventor		6.00		20.	First 100 Feet		30.00	
3. Bath Tub	_1_	6.00			Over 100 Feet		.35/ft.	
 Dishwasher Drinking Fountain 		6.00	1 Telesco	27.	Storm Building Drain			
6. Ejectors or Pump		6.00 6.00			First 100 Feet Over 100 Feet		30.00	
7. Floor Drain		6.00		2.8	Manhole		.35/ft. 10.00	
8. Garbage Grinder		6.00		29.			10.00	
9. Grease Trap		6.00		30.	Water Service			
10. Hose Bibb 11. Laundry Tray		6.00			First 100 Ft. Lateral		30.00	
12. Lavatory	3	6.00 6.00		31	Over 100 Ft. Lateral Sanitary Building Sewer		.35/ft.	
13. Shower	T.	6.00		51.	First 100 Ft. Lateral		30.00	
14. Sink		6.00			Over 100 Ft. Lateral		.35/ft,	
15. Site Drain		6.00		32.	Storm Building Sewer			
16. Slop Sink17. Storm Sewer Conductor		6.00 6.00			First 100 Ft. Lateral		30.00	
18. Sump Pump		6.00		33	Over 100 Ft. Lateral Roughing in of Fixtures		.35/ft.	
19. Urinal		6.00		34.		ms	5.00 30.00	
20. Wash Fountain		6.00		35.	Other Fixtures		6.00	
21. Water Closet22. Water Heater	2	6.00						
Gas		6.00						
Electric	~~~	6.00						
23. Water Softener		6.00			MINIMUM PERMIT FEE		50.00	
24. Water Treatment Device		6.00	-		REINSPECTION FEE		50.00	
25. Whirlpool		10.00	-		FAILURE TO CALL FOR INSI	PECTION	50.00	
							i	
							-	
					TOTAL PER	RMIT FEE:	\$50.	00
DOUBLE FEES ARE DUE IF WORK IS STARTED BEFORE PERMIT IS ISSUED								
Revised Jan. 2004								
THE APPLICANT ACRES TO COM						·		

THE APPLICANT AGREES TO COMPLY WITH ALL MUNICIPAL ORDINANCES AND WITH THE CONDITIONS OF THIS PERMIT, UNDERSTANDS THAT THE ISSUANCE OF THE PERMIT CREATES NO LEGAL LIABILITY, EXPRESS OR IMPLIED, OF THE DEPARTMENT, MUNICIPALITY, AGENCY OR INSPECTOR, AND CERTIFIES THAT ALL THE ABOVE INFORMATION IS ACCURATE. FAILURE TO COMPLY MAY RESULT IN SUSPENSION OR REVOCATION OF THIS PERMIT OR OTHER PENALTY. PLUMBING PLANS AND SPECIFICATIONS OF THE FIXTURES TO BE INSTALLED IN A NEW OR REMODELED BUILDING SHALL BE SUBMITTED WITH THIS APPLICATION IN ACCORDANCE WITH COMM. 82.20 OF THE STATE OF WISCONSIN PLUMBING CODE. FINAL INSPECTIONS ARE MANDATORY. PLEASE HAVE PERMIT NUMBER AND ADDRESS WHEN REQUESTING INSPECTIONS. PLEASE GIVE AT LEAST 24 HOURS NOTICE.

SIGNATURE OF PLUMBER

Dale Halliburton

DATE: 5 406



REGISTRATION NUMBER CC15-0024

VILLAGE OF BROWN DEER

4800 W GREEN BROOK DR BROWN DEER, WI 53223

	THIS IS TO CERTIFY THAT REGISTRATION HAS BEEN MADE BY: $$ HA	RRIS RANDY
--	--	------------

WITH THE RESPONSIBLE AGENT BEING: HARRIS RANDY

FOR THE PROPERTY LOCATED ON THE FOLLOWING:

ADDRESS

3435 W PELICAN LN

OWNER

HARRIS RANDY

Stipulations

Comments

IN ACCORDANCE WITH PROVISIONS OF ORDINANCES OF VILLAGE OF BROWN DEER.

DATE OF APPLICATION: 03/25/2015

EXPIRATION DATE: 03/25/2016

IS HEREBY ACKNOWLEDGED

CODE OFFICIAL



Village of Brown Deer

4800 W. Green Brook Dr. Brown Deer, WI 53223 414-371-3030 / Fax 414-371-3045

(PLEASE TYPE OR PRINT WITH BALL POINT PEN)

PERMIT NO:

cc 15 - 0024

CODE COMPLIANCE APPLICATION

Type of Occupancy ⊠ One & Two Family □ Multi-Family

Property Address:		
3435 W. Pelican Ln		
IS PROPERTY VACANT? Yes I No	If "YES" what is the Lock Box code & lo	cation?
	1125	
CURRENT Owner:	Email	Telephone
Randy Harris Mailing Address:	rharris 7032@gmail.10	1312-231-4410
Mailing Address: /	City	State Zip Code
1526 Wesley AV	Berwyn	IL 60402
Agent for Owner/Property:	Email	Telephone (cell)
Julie Clark	julie@ homesbyjulieckirk.com Contact Person (Print Name)	414-379-4566
Real Estate Company	Contact Person (Print Name)	Telephone (office)
Realty Executives Integrity Address:	Julie Clark	414-379-4566
Address:	City	State Zip Code
412 E. Silver Spring Dr FUTURE Owner:	Milwarkee	WI 53217
(Print Name)	Email	Telephone
Deborah + Jeffrey Woods		Man 110
Mailing Address /	City	State 216/7 2 5 2015
Cash or Check payable to: The Village of Brown Deer	TOTAL PERMIT FEE	\$ 150.00
THE VIHAGE OF DIOWIT DEEL	(Fee is Non-Refundable)	

The premises at the above referenced address shall be brought into compliance prior to closing, but not later than the specified date listed in the Code Compliance Violation letter (if any apply), upon which time a re-inspection must be conducted and the Certificate of Compliance may be obtained for the purpose of closing. If the buyer of this property is purchasing the property in an "AS-IS" condition, the new owner agrees to assume all of the responsibility for correcting the outstanding code violations as listed in the Code Compliance Violation letter. The buyer must notify this office, agree and sign the "Code Compliance Responsibility Agreement", of their intentions and a "Conditional" Certificate of Compliance may be issued for use at the time of closing. If a change of ownership takes place prior to the issuance of a final or conditional certificate, the seller and buyer shall be jointly liable and responsible for making all said corrections. Additionally, any Real Estate brokerage, broker, sales associate, attorney, or agent for a buyer or seller of real estate in the Village of Brown Deer who knowingly contributes to the failure to produce a Final or Conditional Certificate of Compliance as required shall be deemed to have violated the provisions of this Chapter and subject to penalty set forth in the Village of Brown Deer Code of Ordinances.

It is Hereby Agreed between the undersigned as owner or his/her agent/representative, and the Village of Brown Deer, that for and in consideration of the premises listed above; all violations found, if any, are required to be corrected in a timely manner. All permits and inspections that are required will be expeditiously obtained and completed in the time allowance that is specified in the Code Compliance letter, and before any work is started and/or concealed, in accordance with the ordinances of the Village of Brown Deer, and to obey any and all lawful orders of the Building Inspector of the Village of Brown Deer, and all State Laws relating to the construction, alteration, repairs, removal and safety of all buildings and all other structures and all permanent building equipment.

A Certificate of Compliance will not be issued unless repairs ordered by the building inspector are performed. Please have permit number and address available when requesting inspections. Please Give At Least 24 Hours Notice.

FINAL INSPECTIONS ARE MANDATORY.

Signature Of Applicant: Revised 4/20/2013 (If Owners signature, I acknowledge)	dge that I have read and understand the cautionary and statute statements	Date: 3/25/2015
Randy F	Print Name / Relationship to Property	



COMMUNITY SERVICES DEPARTMENT INSPECTION DIVISION 4800 West Green Brook Drive Brown Deer, Wisconsin 53223

March 26, 2015

Randy Harris 3435 W. Pelican Ln. Brown Deer, WI 53209

Re: Certificate of Compliance Inspection

To Randy:

A recent inspection of the dwelling, located at 3435 W. Pelican Ln., disclosed the following violations of the Brown Deer Code of Ordinances:

UNIFORM DWELLING CODE

SPS 321.097

All one and two family dwellings in the State of Wisconsin must have an approved carbon monoxide alarm installed on every floor level of each residential unit if the dwelling contains a fossil fuel powered appliance which is within the interior of the building structure. A CO2 alarm is also required in the basement of this dwelling.

BROWN DEER MUNICIPAL CODE

Section 1-1.05 (b)

Every interior wall, floor and ceiling must be capable of affording privacy, kept in a reasonably good state of repair and maintained so as to permit them to be kept in a clean and sanitary condition:

Block foundation walls showed signs of shear, and step cracks in unfinished sections of basement – north, east, & south walls. Provide foundation repair report from licensed contractor or engineer's report.

NATIONAL ELECTRICAL CODE

The following electrical code violations must be reviewed by a licensed electrical contractor and corrected to meet the minimum standards of the National Electrical Code:

GFCI protected receptacles are required within 6 feet of water - kitchen (2). Provide approved connector where wires enter garbage disposal – kitchen sink.

Replace missing cover plates at receptacles in basement – near sump pump closet.

Incandescent fixtures with open or partially enclosed lamps and pendant fixtures or lampholders are not permitted in closets. Replace pull chain lights in basement closet under stairs and wire per NEC.

The premises at the above address shall be brought into compliance prior to closing but not later than May 26, 2015, upon which time a re-inspection must be conducted and the Certificate of Compliance may be obtained for closing. If the buyer of this property agrees to assume responsibility for correcting the outstanding code violations as listed in this letter, said buyer must notify this office, in writing, of his and/or her intentions and a conditional certificate may be issued. If a change of ownership takes place prior to the issuance of a final or conditional certificate, the seller and buyer shall be jointly and severally liable and responsible for making said corrections. Additionally, any real estate brokerage, broker, sales associate, attorney, or agent for a buyer or seller of real estate in the Village of Brown Deer who knowingly contributes to the failure to produce a Certificate of Compliance as required shall be deemed to have violated the provisions of this Chapter and subject to penalty set forth in the Village of Brown Deer Code of Ordinances.

Please notify my office at (414) 371-3030 or email: kradtke@browndeerwi.org when the corrections have been made so a re-inspection can be conducted and the Certificate of Compliance issued.

Sincerely,

Kirk Radtke Building Inspector

Office: 414.371.3030 - FAX: 414.371.3045 - E-Mail: inspection@browndeerwi.org - WWW.BROWNDEERWI.ORG

Milwaukee, WI 5322: GOWNER Randy Harrys OWNER Randy Harrys PHONE PHONE PHONE PHONE PHONE AGE OF BLDG. OWNED FOR PROBLEMS FOR CONSTRUCTION DEPTH DRAINTILE SUMP PUMP YRS. YRS. YRS. YRS.		NATERPROOFING & FOUNDATION SPECIALISTS
DEPARTMENT WATER PROPER HATTIS WHEN RANGY HATTIS ADDRESS, 3435 W PCINCOL LOAR ADDRESS, 3435 W PCINCOL LOAR PHONE 312-231-4410 DATE 4 19/15 AGE OF BLDG. OWNED FOR PROBLEMS FOR CONSTRUCTION DEPTH DRAINTILE SLAMP PUMP WYRS YRS. WRS. W	GAINISH	605 W Waterford Avenue
OUTSIDE EXCAVATION METHOD EXCAVATE TO FOOTINGS AND HAUL AWAY CLAY STRAIGHTEN WALL WALL SAMOST REASONS TO STRAIGHT HIGH INTEREST CANCES IN STANDARDS OUTSIDE EXCAVATION METHOD EXCAVATE TO FOOTINGS AND HAUL AWAY CLAY STRAIGHTEN WALLS AS MOST REASONLABLY POSSIBLE AND TUCKPOINT MAJOR CRACKS SAL WALL WITH SEALMASTIC WATERPROOPING CLEAN BOLT EXPOSED BLEEDERS AND STRAIL STORE TO WITHIN 18" OF GRADE COVER STONE WITH FILTERING LABOCATE PASHER AND ADD TOPSOIL FOR PROPER SLOPE AWAY INSTALL STEEL WALL MEMBERS FER WATER STANDARDS INSTALL STEEL WALL MEMBERS FER WATER STANDARDS INSTALL STEEL WALL MEMBERS FER WATER STANDARDS INSTALL NEW DEARNILE AND CONSTRUCTION CLEAN BLEEDERS TO EXTERIOR DEARNILE O DRILL BLOCK CORES AND TEST HOLES ON STALL NEW DEARNILE AND CONSTRUCTION TO STAND ADD TOPSOIL FOR PROPER SLOPE AWAY COVER DRAINTILE WITH PROPER FILTERING STONE OF REPLACE FLOOR AREA REMOVED Front Creat CLEAN OF THE STANDARDS TO SERVICE AND TEST HOLES SLOPE OF THE STANDARDS TO SERVICE AND TEST HOLES ON THE STANDARDS TO SERVICE AND TEST HOLES STANDARD OF THE STANDARDS TO SERVICE AND DEFECTIVE WORK INCLUDING LABOR REFELLSWORTH NOTE THIS PROPOSAL MAY BE STANDARD NOTE: This proposal may be withdrawn by us if not accepted within days. TOTAL COST DEPOSIT ON START FOUNDATION REFELLSWORTH Note: This proposal may be withdrawn by us if not accepted within days. THAY READ THE REVERSE SIDE OF THIS PROPOSAL AND UNDERSTAND THIS AGREEMENT TO SERVICE ANY DEFECTIVE WORK INCLUDING LABOR ANATERIALS. POR GAIDISH FOUNDATIONS, SPECIFICATIONS, PRICES AND THE STANDARDS TO SERVICE ANY DEFECTIVE WORK INCLUDING LABOR ANTERIALS POR GAIDISH FOUNDATIONS, SPECIFICATIONS, PRICES AND TOTAL COST DEPOSIT ON START TO SERVICE ANY DEFECTIVE WORK INCLUDING LABOR ANTERIALS POR GAIDISH FOUNDATIONS, SPECIFICATIONS, PRICES AND TOTAL COST DEPOSIT ON START TOTAL COST DEPOSIT ON START TOTAL COST DEPOSIT ON START TOTAL COST DEPOSIT ON STANDARDS TOTAL COST DEPOSIT ON STANDARDS TOTAL COST TOTAL COST DEPOSIT ON STAN	EQUINDATION CO.	Milwaukee, WI 53223
ADDRESS. 3435 W PCINCO LOAK ADDRESS. 3435 W PCINCO LOAK PHONE 312-231-4410 DATE 1915 AGE OF BLDG. OWNED FOR PROBLEMS FOR CONSTRUCTION DEPTH DRAINTILE SUMP PUMP ANALYSIS. Chick wolk 2 wills how shar Cracks, 1 shep Majund will 1/9 to 2/2 wills how shar Cracks, 1 shep Majund will 1/9 to 2/2 wills how shar Cracks, 1 shep Majund will 1/9 to 2/2 wills how shar Cracks, 1 shep MAGIND WALL WITH SEALMANTE WAIDDRESSELE AND TUCKPOINT MAJOR CRACKS SEAL WALL WITH SEALMANTE WAIDENSALLEN POSSIBLE AND TUCKPOINT MAJOR CRACKS SEAL WALL WITH SEALMANTE WAIDENSALLEN POSSIBLE AND TUCKPOINT MAJOR CRACKS ONE STAIL STEEL WALL MEMBERS PER WAFRP STANDARDS INSTALL SEEL WALL MEMBERS PER WAFRP STANDARDS INSTALL SEEL WALL MEMBERS PER WAFRP STANDARDS INSTALL NEW DRAINTILE AND CONNECT SYSTEM 0 INSTALL DELUXE WALL DRAIN COVER DRAINTILE WITH PROPER FILTERING STONE 0 REPLACE FLOOR AREA REMOVED That Crack Cover Of Draintile with PROPER FILTERING STONE 0 REPLACE FLOOR AREA REMOVED That Crack Cover Of Draintile with Proper of the Stap 9' From Cour Of the Wall Members of Wall Members	Basement Waterproofing	(111) 202 200
AGE OF BILDS. OWNED FOR PROBLEMS FOR CONSTRUCTION DEPTH DRANTILE SUMP PUMP AGE OF BILDS. OWNED FOR PROBLEMS FOR CONSTRUCTION DEPTH DRANTILE SUMP PUMP YRS YRS YRS YRS ANALYSIS C Nucle Yolk 2 wells have shar Cracks, I shap MAGINE WILL YOLK 2 wells have shar Cracks, I shap MAGINE WILL YOLK 2 wells have shar Cracks, I shap OUTSIDE EXCAVATION METHOD EXCAVATE TO FOOTINGS AND HAUL AWAY CLAY STRAIGHTEN WALLS AS MOST REASONLABLY POSSIBLE AND TUCKPOINT MAJOR CRACKS SEAL WALL WITH SEALMASTIC WATEPROOPING CLEAN OUT EXPOSED BLEEDERS AND INSTADE TO WITHIN 18" OF GRADE BACKFILL WITH INDIFFERENCE HIS PROOPING TO WITHIN 18" OF GRADE COVER STONE WITH FILTERENS AND INSTADE TO WITHIN 18" OF GRADE COVER STONE WITH FILTERENS FOR WAFP STANDARDS INSTALL STEEL WALL MIRMERS FER WAFP STANDARDS INSTALL STEEL WALL MIRMERS FER WAFP STANDARDS INSTALL STEEL WALL MIRMERS FER WAFP STANDARDS INSTALL NEW DEAINTILE AND CONNECT SYSTEM INSTALL BELIEVE WALL DRAIN COVER DRAINTILE WITH PROPER FILTERING STONE IN REPLACE FLOOR AREA REMOVED FIRST Count Of the Crack No Shape outsule Each of Stap 9" First Crack Cuell Vy" out of Plunk (11" From Came) Shape outsule Each of Stap 9" First Crack Of The Crack No Shape outsule Each of Stap 9" First Crack No Shape outsule Each of Stap 9" First Crack No Shape outsule Each of Stap 9" First Crack No Shape outsule Each of Stap 9" First Crack No Shape outsule Each of Stap 9" First Crack No Shape outsule Each of Stap 9" First Crack No Shape outsule Each of Stap 9" First Crack No Shape outsule Each of Stap 9" First Crack No Shape outsule Each of Stap 9" First Crack No Shape outsule Each of Stap 9" First Crack No Shape outsule Each of Stap 9" First Crack No Shape outsule Each of Stap 9" First Crack No Shape outsule Each of Stap 9" First Crack No Shape outsule Each	O WINEX	
AGE OF BLDG. OWNED FOR PROBLEMS FOR CONSTRUCTION DEPTH DRAINTILE SUMP PUMP AGE OF BLDG. OWNED FOR PROBLEMS FOR CONSTRUCTION DEPTH DRAINTILE SUMP PUMP YRS. YRS. YRS. ONSTAIL SUMP PUMP OUT ALL SAN OCT REACKS J SAND THE DEACKS J SAND THE DEACKS J SAND THE DEACKS J SAND THE SAND	ADDRESS 3435 W Pelicon Lane	PHONE 312-231 - 4410
ARE OF BLDG. WERE FOR PROBLEMS FOR THE CONSTRUCTION OF THE PROBLEMS FOR THE CONSTRUCTION OF THE CONSTRUCT	R O. c (2)88 200 53209	DATE 4 19/15
ANALYSIS Chuck wolk 2 wells have shar Cracks, 1 shep MAGIND COM! 19 " to 3/2 cut of Plumb OUTSIDE EXCAVATION METHOD EXCAVATE TO FOOTINGS AND HAUL AWAY CLAY STRAIGHTEN WALLS AS MOST REASONLABLY POSSIBLE AND TUCKPOINT MAJOR CRACKS STRAIGHTEN WALLS AS MOST REASONLABLY POSSIBLE AND TUCKPOINT MAJOR CRACKS SEAL WALL WITH SEALMASTIC WATERPROOFING CLEAN MOUT EXPOSED BLEEDERS AND INSTALL NEW DRAINTILLE BACKFILL WITH LIGHTWEIGHT #1 CLEAR STONE TO WITHIN 18" OF GRADE COVER STONE WITH EITERING LAND INSTALL NEW DOTORSOIL FOR PROPER SLOPE AWAY INSTALL STEEL WALL MEMBERS PER WARRY STANDARDS INSTALL STEEL WALL MEMBERS PER WARRY STANDARDS INSTALL STEEL WALL MEMBERS PER WARRY STANDARDS INSTALL NEW DRAINTILE AND CONNECT SYSTEM INSTALL DELUXE WALL DRAINTILE CLEAN BLEEDERS TO EXTERIOR DRAINTILE ID DRILL BLOCK CORES AND TEST HOLES INSTALL NEW DRAINTILE AND CONNECT SYSTEM INSTALL DELUXE WALL DRAINTILE CLEAN BLEEDERS TO EXTERIOR DRAINTILE ID DRILL BLOCK CORES AND TEST HOLES INSTALL NEW DRAINTILE AND CONNECT SYSTEM INSTALL DELUXE WALL DRAIN COVER DRAINTILE WITH PROPER FILTERING STONE ID REPLACE ELOOR AREA REMOVED TOTAL COVER DRAINTILE WITH PROPER FILTERING STONE ID REPLACE ELOOR AREA REMOVED TOTAL CORT STAND ON THE CONDITIONS OF WALL NO. SERVICE OF THE STANDARDS OTHER PROPOSIT ON START BALANCE PAY ON TOTAL COST UNDERSTOND OF TYEARS STANDARD ON START BALANCE PAY ON ST	AGE OF BLDG. OWNED FOR	JCTION DEPTH DRAINTILE SUMP PUMP
OUTSIDE EXCAVATION METHOD EXCAVATE TO FOOTINGS AND HAUL AWAY CLAY STRAIGHTEN WALLS AS MOST REASONLABLY POSSIBLE AND TUCKPOINT MAJOR CRACKS STRAIGHTEN WALLS AS MOST REASONLABLY POSSIBLE AND TUCKPOINT MAJOR CRACKS SEAL WALL WITH SEALMASTIC WATERPROOFING COLOR STONE WITH FLITERING LANDSCAPE FABRIC AND ADD TOPSOIL FOR PROPER SLOPE AWAY INSTALL STEEL WALL MEMBERS PER WAPR STANDARDS INSTALL NEW DRAINTILE CLEAN BLEEDERS TO EXTERIOR DRAINTILE CLEAN BLEEDERS TO EXTERIOR DRAINTILE COVER PRAINTILE WITH PROPER FILTERING STONE © REPLACE FLOOR AREA REMOVED Front Crack Cuall Vy out of Plunk (11' From Cour) Steup outside End of Stap 9' From Cour Nother Management of Stap 9' From Cour Nother Management of Stap 9' From Cours Nother Management	110.	shear Cracks, 1 step
OUTSIDE EXCAVATION METHOD EXCAVATE TO FOOTINGS AND HAUL AWAY CLAY STRAIGHTEN WALLS AS MOST REASONLABLY POSSIBLE AND TUCKPOINT MAJOR CRACKS SEAL WALL WITH SEALMASTIC WATERPROOFING CLEAN OUT EXPOSED BLEEDERS AND INSTALL NEW DRAINTILE CLEAN OUT EXPOSED BLEEDERS AND INSTALL NEW DRAINTILE COVER STONE WITH LICHTWEIGHT #1 CLEAR STONE TO WITHIN 18" OF GRADE COVER STONE WITH FILTERING LANDSCAPE FABRIC AND ADD TOPOIL FOR PROPER SLOPE AWAY INSTALL STEEL WALL MEMBERS PER WARRP STANDARDS INSTALL NEW DRAINTILE AND CONNECT SYSTEM INSTALL DELUXE WALL DRAIN CLEAN BLEEDERS TO EXTERIOR DRAINTILE DRAIL BELOK CORES AND TEST HOLES INSTALL NEW DRAINTILE WITH PROPER FILTERING STONE INSTALL DELUXE WALL DRAIN COVER DRAINTILE WITH PROPER FILTERING STONE REPLACE FLOOR AREA REMOVED THAT Crack of the steep of the		Ь
□ EXCAVATE TO FOOTINGS AND HAUL AWAY CLAY □ STRAIGHTEN WALLS AS MOST REASONLABLY POSSIBLE AND TUCKPOINT MAJOR CRACKS □ SEAL WALL WITH SEALMASTIC WATERPROOFING □ CLEAN OUT EXPOSED BLEEDERS AND INSTALL NEW DRAINTILE □ BACKFILL WITH LIGHTWEIGHT & ICLEAR STONE TO WITHIN 18" OF GRADE □ COVER STONE WITH FILTERING LANDSCAPE FABRIC AND ADD TOPSOIL FOR PROPER SLOPE AWAY □ INSTALL STEEL WALL MEMBERS PER WARPR STANDARDS INSTALL STEEL WALL MEMBERS PER WARPR STANDARDS INSTALL STEEL WALL MEMBERS PER WARPR STANDARDS INSTALL NEW DRAINTILE □ CLEAN BLEEDERS TO EXTERIOR DRAINTILE □ DRILL BLOCK CORES AND TEST HOLES □ INSTALL NEW DRAINTILE AND CONNECT SYSTEM □ INSTALL DELUXE WALL DRAIN □ COVER DRAINTILE WITH PROPER FILTERING STONE □ REPLACE FLOOR AREA REMOVED FIRST COVER DRAINTILE WITH PROPER FILTERING STONE □ REPLACE FLOOR AREA REMOVED FIRST COULT NOT THE WORLD FOR THE WARP HOLE CHARLY W' OUT OF Plunb (I' From Court Staup outsule End of Staup 9' From Court Nature May have Charly the Weather May have TOTAL COST DEPOSIT ON START TO SERVICE ANY DEFECTIVE WORK, INCLUDING LABOR BALANCE PAY ON COMPLETION COMPLETION Note: This proposal may be withdrawn by us if not accepted within	Majord Charle 17 11	
□ EXCAVATE TO FOOTINGS AND HAUL AWAY CLAY □ STRAIGHTEN WALLS AS MOST REASONLABLY POSSIBLE AND TUCKPOINT MAJOR CRACKS □ SEAL WALL WITH SEALMASTIC WATERPROOFING □ CLEAN OUT EXPOSED BLEEDERS AND INSTALL NEW DRAINTILE □ BACKFILL WITH LIGHTWEIGHT & I CLEAR STONE TO WITHIN 18" OF GRADE □ COVER STONE WITH FILTERING LANDSCAPE FABRIC AND ADD TOPSOIL FOR PROPER SLOPE AWAY □ INSTALL STEEL WALL MEMBERS PER WAFRY STANDARDS INSTALL NEW DRAINTILE □ CLEAN BLEEDERS TO EXTERIOR DRAINTILE □ DRILL BLOCK CORES AND TEST HOLES □ INSTALL NEW DRAINTILE AND CONNECT SYSTEM □ INSTALL DELUXE WALL DRAIN □ COVER DRAINTILE WITH PROPER FILTERING STONE □ REPLACE FLOOR AREA REMOVED FIRST COALL (LEAN BY " out of Plunk (I' From Cour) Skeup outside End of Storp 9' From Cour. Nature movement of Storp with weather may have contributed to Crack. No Scrius movement on wall. Other was movement on wall. No Pollem, movement Cracks or Something on extens of Horizontal Cracks on wall. No Work necessory TOTAL COST DEPOSIT ON START DEPOSIT ON START DEPOSIT ON START DEPOSIT ON START TO SERVICE ANY DEFECTIVE WORK, INCLUDING LABOR & MATERIALS. PAY ON COMPLETION FOUNDATION. THE CONDITIONS, SPECIFICATIONS, PRICES AND LIHAYE READ THE REVERSE SIDE OF THIS PROPOSAL AND UNDERSTAND THIS AGREEMENT TO SIBILIFET TO THOSE CONDITIONS. THE CONDITIONS, SPECIFICATIONS, PRICES AND		
□ EXCAVATE TO FOOTINGS AND HAUL AWAY CLAY □ STRAIGHTEN WALLS AS MOST REASONLABLY POSSIBLE AND TUCKPOINT MAJOR CRACKS □ SEAL WALL WITH SEALMASTIC WATERPROOFING □ CLEAN OUT EXPOSED BLEEDERS AND INSTALL NEW DRAINTILE □ BACKFILL WITH LIGHTWEIGHT & I CLEAR STONE TO WITHIN 18" OF GRADE □ COVER STONE WITH FILTERING LANDSCAPE FABRIC AND ADD TOPSOIL FOR PROPER SLOPE AWAY □ INSTALL STEEL WALL MEMBERS PER WAFRY STANDARDS INSTALL NEW DRAINTILE □ CLEAN BLEEDERS TO EXTERIOR DRAINTILE □ DRILL BLOCK CORES AND TEST HOLES □ INSTALL NEW DRAINTILE AND CONNECT SYSTEM □ INSTALL DELUXE WALL DRAIN □ COVER DRAINTILE WITH PROPER FILTERING STONE □ REPLACE FLOOR AREA REMOVED FIRST COALL (LEAN BY " out of Plunk (I' From Cour) Skeup outside End of Storp 9' From Cour. Nature movement of Storp with weather may have contributed to Crack. No Scrius movement on wall. Other was movement on wall. No Pollem, movement Cracks or Something on extens of Horizontal Cracks on wall. No Work necessory TOTAL COST DEPOSIT ON START DEPOSIT ON START DEPOSIT ON START DEPOSIT ON START TO SERVICE ANY DEFECTIVE WORK, INCLUDING LABOR & MATERIALS. PAY ON COMPLETION FOUNDATION. THE CONDITIONS, SPECIFICATIONS, PRICES AND LIHAYE READ THE REVERSE SIDE OF THIS PROPOSAL AND UNDERSTAND THIS AGREEMENT TO SIBILIFET TO THOSE CONDITIONS. THE CONDITIONS, SPECIFICATIONS, PRICES AND		
STRAIGHTEN WALLS AS MOST REASONLABLY POSSIBLE AND TOCKPOINT IN ACCORDANCE OF STRAIGHTEN WALLS AS MOST REASONLABLY POSSIBLE AND TOCKPOINT IN ACCORDANCE OF THE PROPER SALMASTIC WATERPROOFING OF CLEAN OUT EXPOSED BLEEDERS AND INSTALL NEW DRAINTILE OF GRADE OCVER STONE WITH FILTERING LANDSCAPE FABRIC AND ADD TOPSOIL FOR PROPER SLOPE AWAY INSTALL STEEL WALL MEMBERS PER WAFRP STANDARDS INSTALL NEW DRAINTILE AND CONNECT SYSTEM ON WALL AND OLD DRAINTILE OCCEAN BLEEDERS TO EXTERIOR DRAINTILE OF DRAIL BLOCK CORES AND TEST HOLES. INSTALL NEW DRAINTILE AND CONNECT SYSTEM ON STALL DELUXE WALL DRAIN OCCUPANTILE WITH PROPER FILTERING STONE OF REPLACE FLOOR AREA REMOVED. Front Creat Stup outside End of Storp 9' From Court Office of Storp 9' From Court Offic	OUTSIDE EXCAVA	ATION METHOD
STRAIGHTEN WALLS AS MOST REASONLABLY POSSIBLE AND TOCKPOINT IN ACCORDANCE OF STRAIGHTEN WALLS AS MOST REASONLABLY POSSIBLE AND TOCKPOINT IN ACCORDANCE OF THE PROPER SALMASTIC WATERPROOFING OF CLEAN OUT EXPOSED BLEEDERS AND INSTALL NEW DRAINTILE OF GRADE OCVER STONE WITH FILTERING LANDSCAPE FABRIC AND ADD TOPSOIL FOR PROPER SLOPE AWAY INSTALL STEEL WALL MEMBERS PER WAFRP STANDARDS INSTALL NEW DRAINTILE AND CONNECT SYSTEM ON WALL AND OLD DRAINTILE OCCEAN BLEEDERS TO EXTERIOR DRAINTILE OF DRAIL BLOCK CORES AND TEST HOLES. INSTALL NEW DRAINTILE AND CONNECT SYSTEM ON STALL DELUXE WALL DRAIN OCCUPANTILE WITH PROPER FILTERING STONE OF REPLACE FLOOR AREA REMOVED. Front Creat Stup outside End of Storp 9' From Court Office of Storp 9' From Court Offic	THE THE PROPERTY OF A VICE AND INVALID A SULAV CLAV	
INSTALL STEEL WALL MEMBERS PER WARRY STANDARDS INSIDE DRAINTILE REMOVE FLOOR SECTION APPROXIMATELY 1 FT. WIDE FROM WALL AND OLD DRAINTILE CLEAN BLEEDERS TO EXTERIOR DRAINTILE DRILL BLOCK CORES AND TEST HOLES INSTALL NEW DRAINTILE AND CONNECT SYSTEM INSTALL DELUXE WALL DRAIN COVER DRAINTILE WITH PROPER FILTERING STONE REPLACE FLOOR AREA REMOVED Front Crock Carl	☐ STRAIGHTEN WALLS AS MOST REASONLABLY POS ☐ SEAL WALL WITH SEALMASTIC WATERPROOFING ☐ CLEAN OUT EXPOSED BLEEDERS AND INSTALL NE	EW DRAINTILE TO WITHIN 18" OF GRADE
REMOVE FLOOR SECTION APPROXIMATELY I FT. WIDE FROM WALL AND OLD DRAINTILE CLEAN BLEEDERS TO EXTERIOR DRAINTILE DRILL BLOCK CORES AND TEST HOLES INSTALL NEW DRAINTILE AND CONNECT SYSTEM INSTALL DELUXE WALL DRAIN COVER DRAINTILE WITH PROPER FILTERING STONE REPLACE FLOOR AREA REMOVED Front Creck Cuall Y4" out of Plunb (11' from Court) Steep outside End of Steep 9' From Court. Natural movement of Steep outside End of Steep 9' From Court. Natural movement of Steep outside End of Steep 9' From Court. Natural movement of Steep outside To Creck. No Scrives movement on wall. Other wall measured Yv" out of Plunb with No Pooltin, movement Crecks or Something on extens of Horizontal Crecks on wall. No Pooltin, movement Crecks or Something on extens of Horizontal Crecks on wall. No Work necessary TOTAL COST DEPOSIT ON START TO SERVICE ANY DEFECTIVE WORK, INCLUDING LABOR & MATERIALS. FOR GAIDISH FOUNDATION INTEREST SEED OF THIS PROPOSAL AND UNDERSTAND THIS AGREEMENT IS SUBJECT TO THOSE CONDITIONS. THE CONDITIONS, SPECIFICATIONS, PRICES AND	☐ INSTALL STEEL WALL MEMBERS PER WAFRP STAI	NDARDS
CLEAN BLEEDERS TO EXTERIOR DRAINTILE - DRILL BLUCK CURES AND 1651 HORDERS INSTALL NEW DRAINTILE AND CONNECT SYSTEM INSTALL DELUXE WALL DRAIN COVER DRAINTILE WITH PROPER FILTERING STONE REPLACE FLOOR AREA REMOVED Front Creach Cuell 1/4" out of Plunds (11' from Courc) Steup outsich End of Stoup 9' From Cource Nature Movement of Stoup outsich End of Stoup 9' From Cource Nature Movement of Stoup outsich End of Stoup 9' From Cource Nature Movement of Stoup outsich End of Stoup 9' From Cource Nature Natur	INSIDE DRA	AINTILE
CLEAN BLEEDERS TO EXTERIOR DRAINTILE - DRILL DELUXE WALL DRAIN NSTALL DELUXE WALL DRAIN COVER DRAINTILE WITH PROPER FILTERING STONE REPLACE FLOOR AREA REMOVED Trent Creach Cuell 14" out of Plund (11' from Cour) Steep outside End of Steep 9' From Cour. Natural movement of Steep outside End of Steep 9' From Cour. Natural movement of Steep outside End of Steep 9' From Cour. Natural movement of Steep outside End of Steep 9' From Cour. Natural movement of Steep outside End of Steep 9' From Cour. Natural movement of Steep outside End of Steep 9' From Cour. Natural movement of Steep outside End of Steep 9' From Cour. Natural movement of Steep outside End of Steep 9' From Cour. Natural movement of Steep outside End of Steep 9' From Cour. Natural Movement of Steep 9' From Cour	D REMOVE FLOOR SECTION APPROXIMATELY 1 FT.	WIDE FROM WALL AND OLD DRAINTILE
Front Crack Chall 14" out of Plunt (11" from Com) Steep outside End of Stoep 9" From Cover. Nature movement of Stoep outside End of Stoep 9" From Cover. Nature movement of Stoep with weather may have Contributed to Crack. No Series movement on well. Other healt measured 1/4" out of Plunts with No Poster, movement Cracks or Something on exterior of How over time Contributed to Cracks. Pant in side of Cracks Indicate Cracks have been there for a while. No lever recesory TOTAL COST DEPOSIT ON START TO SERVICE ANY DEFECTIVE WORK, INCLUDING LABOR & MATERIALS. FOR GAIDISH FOUNDATION INSTRIBECT TO THOSE CONDITIONS. THE CONDITIONS, SPECIFICATIONS, PRICES AND	TO OF TAX DE PEDEDO TO EVIEDIOD DRAINTILE [1 D]	RILL BLOCK COKES AND TEST HOLES
Front Creek Civil 14" out of Plumb (11' from Courn) Steep outside End of Stoop 9' From Courn Natural movement of Steep with weather may have Contributed to Creek. No Series movement on well. Other wall measured 1/4" out of Plumb with no Horrental Creeks on wall. No Problem, movement Creeks or Something on externs of Horrental Creeks on wall. No Poster, movement Creeks or Something on externs of Horrental Creeks have been thee for a while. No Work necesory TOTAL COST DEPOSIT ON START BALANCE PAY ON MATERIALS. FOR GAIDISH FOUNDATION Note: This proposal may be withdrawn by us if not accepted within days. I HAVE READ THE REVERSE SIDE OF THIS PROPOSAL AND UNDERSTAND THIS AGREEMENT IS SUBJECT TO THOSE CONDITIONS. THE CONDITIONS, SPECIFICATIONS, PRICES AND	TO DICTALL NEW DRAINTILE AND CONNECT SYSTEM	I INSTALL DELUXE WALL DRAIN
Steep outside End of Steep 9' From Cover. Natral movement of Steep outside End of Steep 9' From Cover. Natral movement of Steep with weather may have Contributed to Crick. No Scrius movement on will. Other wall measured /y" out of Plumb with No Horreant Cricks on will. No Poblim, movement Cricks or Something on exterior of Horreant Contributed to Cricks. Point in side of Cricks Indicate Cricks have been three for a while. No work necessary TOTAL COST DEPOSIT ON START TO SERVICE ANY DEFECTIVE WORK, INCLUDING LABOR & MATERIALS. FOR GAIDISH FOUNDATION JEFF ELISWORTH Note: This proposal may be withdrawn by us if not accepted within days. I HAVE READ THE REVERSE SIDE OF THIS PROPOSAL AND UNDERSTAND THIS AGREEMENT IS SIBILIFET TO THOSE CONDITIONS. THE CONDITIONS, SPECIFICATIONS, PRICES AND	COVER DRAINTILE WITH PROPER FILTERING STOP	NE LI REFERENCE PORTE DE LA CONTRACTION DEL CONTRACTION DE LA CONT
Steep outside End of Steep 9' From Cover. Natral movement of Steep outside End of Steep 9' From Cover. Natral movement of Steep with weather may have Contributed to Crick. No Scrius movement on will. Other wall measured /y" out of Plumb with No Horreant Cricks on will. No Poblim, movement Cricks or Something on exterior of Horreant Contributed to Cricks. Point in side of Cricks Indicate Cricks have been three for a while. No work necessary TOTAL COST DEPOSIT ON START TO SERVICE ANY DEFECTIVE WORK, INCLUDING LABOR & MATERIALS. FOR GAIDISH FOUNDATION JEFF ELISWORTH Note: This proposal may be withdrawn by us if not accepted within days. I HAVE READ THE REVERSE SIDE OF THIS PROPOSAL AND UNDERSTAND THIS AGREEMENT IS SIBILIFET TO THOSE CONDITIONS. THE CONDITIONS, SPECIFICATIONS, PRICES AND		
Steep outsich End of Steep 9 from Cour. Natural movement of Stoop with weather may have Contributed to Cruck. Mo Serious movement on wall. Other wall measured 1/4" out of Plumb with no Horreanhal Crucks on wall. No Problem, movement Crucks or Something on exterior of Here over time Contributed to Crucks. Paint in side of Crucks Indicate Crucks have been three for a while. No work necesory TOTAL COST DEPOSIT ON START TO SERVICE ANY DEFECTIVE WORK, INCLUDING LABOR & MATERIALS. FOR GAIDISH FOUNDATION JEFF ELLSWORTH Note: This proposal may be withdrawn by us if not accepted within days. I HAVE READ THE REVERSE SIDE OF THIS PROPOSAL AND UNDERSTAND THIS AGREEMENT IS SIBILIFET TO THOSE CONDITIONS. THE CONDITIONS, SPECIFICATIONS, PRICES AND	Front Crack	
Steep outsich End of Steep 9 from Cour. Natural movement of Stoop with weather may have Contributed to Cruck. Mo Serious movement on wall. Other wall measured My out of Plumb with no Horreantal Crucks on wall. No Problem, movement Crucks or Something on exterior of Here over time Contributed to Crucks. Paint in side of Crucks Indicate Crucks have been three for a while. No work necesory TOTAL COST DEPOSIT ON START OSERVICE ANY DEFECTIVE WORK, INCLUDING LABOR & MATERIALS. FOR GAIDISH FOUNDATION JEFF ELLSWORTH Note: This proposal may be withdrawn by us if not accepted within days. I HAVE READ THE REVERSE SIDE OF THIS PROPOSAL AND UNDERSTAND THIS AGREEMENT IS SIBILIFICT TO THOSE CONDITIONS. THE CONDITIONS, SPECIFICATIONS, PRICES AND	cuall 1/4" out of Plumb (11' From Con	m) Yu (Yy Firshill
Starting Date Completion Date Deposit Gailish Guarantees for a period of years Starting Date Completion Date Deposit Gailish Guarantees for a period of years End and Defective work, including Labor End and Defective work, including Labor End and Defective work including Labor End and Defective within days. Thave read the reverse side of this proposal and understand this agreement is subject to those conditions. The conditions, specifications, prices and	Stup outside End of Stoop 9	
Starting Date Completion Date Deposit Gailish Guarantees for a period of years Starting Date Completion Date Deposit Gailish Guarantees for a period of years End and Defective work, including Labor End and Defective work, including Labor End and Defective work including Labor End and Defective within days. Thave read the reverse side of this proposal and understand this agreement is subject to those conditions. The conditions, specifications, prices and	Fan Cours Natural movement of	F
Scruss movement on wall. Scruss movement on wall. other wall measured 1/4" out of Plumb with no Horizontal Cracks on wall. No Problem, movement Cracks or Something on extense of Hora over the Contributed to Cracks. Part in side of Cracks indicate Cracks have been three for a white. No work necesory TOTAL COST DEPOSIT ON START GAIDISH GUARANTEES FOR A PERIOD OF YEARS TO SERVICE ANY DEFECTIVE WORK, INCLUDING LABOR & MATERIALS. FOR GAIDISH FOUNDATION JEFF ELLSWORTH Note: This proposal may be withdrawn by us if not accepted within days. I HAVE READ THE REVERSE SIDE OF THIS PROPOSAL AND UNDERSTAND THIS AGREEMENT IS SUBJECT TO THOSE CONDITIONS. THE CONDITIONS, SPECIFICATIONS, PRICES AND	al a the weather may have	1/4
Scrius movement on wall. Starting Date	Steel with South No	
other wall measured 1/4" out of Plumb with no Horrental Cricks or wall. No Poblin, morenet Cricks or Something on extens of Horizontal Cricks have been three for a while. No work necessary TOTAL COST DEPOSIT TO SERVICE ANY DEFECTIVE WORK, INCLUDING LABOR & MATERIALS. FOR GAIDISH FOUNDATION JEFFELLSWORTH Note: This proposal may be withdrawn by us if not accepted within days. I HAVE READ THE REVERSE SIDE OF THIS PROPOSAL AND UNDERSTAND THIS AGREEMENT IS SUBJECT TO THOSE CONDITIONS. THE CONDITIONS, SPECIFICATIONS, PRICES AND		34 1/4 - 10 Å
No Problem, movement Crecks or Something an exterior of Home over time Contributed to Crecks. Pant in side of Crecks Indicate Crecks have been three for a while. No work necesory TOTAL COST DEPOSIT GAIDISH GUARANTEES FOR A PERIOD OF YEARS TO SERVICE ANY DEFECTIVE WORK, INCLUDING LABOR & MATERIALS. FOR GAIDISH FOUNDATION JEFF ELLSWORTH Note: This proposal may be withdrawn by us if not accepted within days. I HAVE READ THE REVERSE SIDE OF THIS PROPOSAL AND UNDERSTAND THIS AGREEMENT IS SUBJECT TO THOSE CONDITIONS. THE CONDITIONS, SPECIFICATIONS, PRICES AND	Serius movement on coult.	18 / There's a
No Problem, movement Crecks or Something an exterior of Home over time Contributed to Crecks. Pant in side of Crecks Indicate Crecks have been three for a while. No work necesory TOTAL COST DEPOSIT GAIDISH GUARANTEES FOR A PERIOD OF YEARS TO SERVICE ANY DEFECTIVE WORK, INCLUDING LABOR & MATERIALS. FOR GAIDISH FOUNDATION JEFF ELLSWORTH Note: This proposal may be withdrawn by us if not accepted within days. I HAVE READ THE REVERSE SIDE OF THIS PROPOSAL AND UNDERSTAND THIS AGREEMENT IS SUBJECT TO THOSE CONDITIONS. THE CONDITIONS, SPECIFICATIONS, PRICES AND	11 m. c 0 1/v" out of	Plumb with
No Problem, movement Crecks or Something on externe of Horn over time Contributed to Creates. Point in side of Creates Indicate Creates have been three for a white. No work necesory TOTAL COST DEPOSIT ON START TO SERVICE ANY DEFECTIVE WORK, INCLUDING LABOR # MATERIALS. FOR GAIDISH FOUNDATION JEFF ELLSWORTH Note: This proposal may be withdrawn by us if not accepted within days. I HAVE READ THE REVERSE SIDE OF THIS PROPOSAL AND UNDERSTAND THIS AGREEMENT IS SUBJECT TO THOSE CONDITIONS. THE CONDITIONS, SPECIFICATIONS, PRICES AND	other wall incasured	
Starting Date Completion Date DEPOSIT GAIDISH GUARANTEES FOR A PERIOD OF YEARS TO SERVICE ANY DEFECTIVE WORK, INCLUDING LABOR ### MATERIALS. FOR GAIDISH FOUNDATION JEFF ELLSWORTH I HAVE READ THE REVERSE SIDE OF THIS PROPOSAL AND UNDERSTAND THIS AGREEMENT IS SUBJECT TO THOSE CONDITIONS. THE CONDITIONS, SPECIFICATIONS, PRICES AND	no Horrental Cacas	e sur autour
Starting Date Completion Date DEPOSIT GAIDISH GUARANTEES FOR A PERIOD OF YEARS TO SERVICE ANY DEFECTIVE WORK, INCLUDING LABOR & MATERIALS. FOR GAIDISH FOUNDATION Note: This proposal may be withdrawn by us if not accepted within days. I HAVE READ THE REVERSE SIDE OF THIS PROPOSAL AND UNDERSTAND THIS AGREEMENT IS SUBJECT TO THOSE CONDITIONS. THE CONDITIONS, SPECIFICATIONS, PRICES AND	No roblin, movement checks	To James and Carolina Control of the
Starting Date Completion Date DEPOSIT GAIDISH GUARANTEES FOR A PERIOD OF YEARS TO SERVICE ANY DEFECTIVE WORK, INCLUDING LABOR & MATERIALS. FOR GAIDISH FOUNDATION Note: This proposal may be withdrawn by us if not accepted within days. I HAVE READ THE REVERSE SIDE OF THIS PROPOSAL AND UNDERSTAND THIS AGREEMENT IS SUBJECT TO THOSE CONDITIONS. THE CONDITIONS, SPECIFICATIONS, PRICES AND	Here over time Contributed to	Cracks. Part in side of Cracks
Starting DateCompletion DateDEPOSIT GAIDISH GUARANTEES FOR A PERIOD OFYEARS TO SERVICE ANY DEFECTIVE WORK, INCLUDING LABOR & MATERIALS. FOR GAIDISH FOUNDATION	indicate Cracles have been three	for a while.
Starting DateCompletion DateDEPOSIT GAIDISH GUARANTEES FOR A PERIOD OFYEARS TO SERVICE ANY DEFECTIVE WORK, INCLUDING LABOR & MATERIALS. FOR GAIDISH FOUNDATION	Na Larck necessiv	
Starting DateCompletion DateDEPOSIT GAIDISH GUARANTEES FOR A PERIOD OFYEARS TO SERVICE ANY DEFECTIVE WORK, INCLUDING LABOR & MATERIALS. FOR GAIDISH FOUNDATION	140 (00)	TOTAL COST
GAIDISH GUARANTEES FOR A PERIOD OF YEARS TO SERVICE ANY DEFECTIVE WORK, INCLUDING LABOR & MATERIALS. FOR GAIDISH FOUNDATION JEFF ELLSWORTH Note: This proposal may be withdrawn by us if not accepted within days. I HAVE READ THE REVERSE SIDE OF THIS PROPOSAL AND UNDERSTAND THIS AGREEMENT IS SUBJECT TO THOSE CONDITIONS. THE CONDITIONS, SPECIFICATIONS, PRICES AND		
GAIDISH GUARANTEES FOR A PERIOD OFYEARS TO SERVICE ANY DEFECTIVE WORK, INCLUDING LABOR & MATERIALS. FOR GAIDISH FOUNDATION JEFF ELLSWORTH Note: This proposal may be withdrawn by us if not accepted within days. I HAVE READ THE REVERSE SIDE OF THIS PROPOSAL AND UNDERSTAND THIS AGREEMENT IS SUBJECT TO THOSE CONDITIONS. THE CONDITIONS, SPECIFICATIONS, PRICES AND	Starting Date Completion Date	DEPOSIT
**EAST TO SERVICE ANY DEFECTIVE WORK, INCLUDING LABOR **EAST ON COMPLETION **FOR GAIDISH FOUNDATION **JEFF ELLSWORTH DEFENDED BY US IT NOT ACCEPTED WITHOUT THE PROPOSAL AND UNDERSTAND THIS AGREEMENT IS SUBJECT TO THOSE CONDITIONS. THE CONDITIONS, SPECIFICATIONS, PRICES AND	Julius Santa	ON START \
MATERIALS. FOR GAIDISH FOUNDATION JEFF ELLSWORTH Note: This proposal may be withdrawn by us if not accepted within days. I HAVE READ THE REVERSE SIDE OF THIS PROPOSAL AND UNDERSTAND THIS AGREEMENT IS SUBJECT TO THOSE CONDITIONS. THE CONDITIONS, SPECIFICATIONS, PRICES AND	GAIDISH GUARANTEES FOR A PERIOD OF YEARS	BALANCE
FOR GAIDISH FOUNDATION JEFF ELLSWORTH Note: This proposal may be withdrawn by us if not accepted within days. I HAVE READ THE REVERSE SIDE OF THIS PROPOSAL AND UNDERSTAND THIS AGREEMENT IS SUBJECT TO THOSE CONDITIONS. THE CONDITIONS, SPECIFICATIONS, PRICES AND		PAYON
FOUNDATION JEFF ELLSWORTH Note: This proposal may be withdrawn by us if not accepted within days. I HAVE READ THE REVERSE SIDE OF THIS PROPOSAL AND UNDERSTAND THIS AGREEMENT IS SUBJECT TO THOSE CONDITIONS. THE CONDITIONS, SPECIFICATIONS, PRICES AND	W DISTERIOLO.	COMPLETION
I HAVE READ THE REVERSE SIDE OF THIS PROPOSAL AND UNDERSTAND THIS AGREEMENT IS SUBJECT TO THOSE CONDITIONS. THE CONDITIONS, SPECIFICATIONS, PRICES AND		Note: This proposal may be withdrawn
I HAVE READ THE REVERSE SIDE OF THIS PROPOSAL AND UNDERSTAND THIS AGREEMENT IS SUBJECT TO THOSE CONDITIONS. THE CONDITIONS, SPECIFICATIONS, PRICES AND	FOUNDATION	by us if not accepted within days.
IS SUBJECT TO THOSE CONDITIONS. THE CONDITIONS, SPECIFICATIONS, FRICES AND		
IS SUBJECT TO THOSE CONDITIONS. THE CONDITIONS, SPECIFICATIONS, FRICES AND	I HAVE READ THE REVERSE SIDE OF THIS PROPOSAL AN	ND UNDERSTAND THIS AGREEMENT
TERMS ARE SATISFACTORY AND HEREBY ACCEPTED.	IS SUBJECT TO THOSE CONDITIONS. THE CONDITIONS,	SPECIFICATIONS, PRICES AND
	TERMS ARE SATISFACTORY AND HEREBY ACCEPTED.	
Signature Date Signature Date Date	Simplifie Date Si	ignatureDate

YFILOW - SHOP COPY

WHITE - OFFICE COPY

PINK - CUSTOMER COPY