



# Village of Brown Deer

*✓ Non well  
ABAND  
REPORT*

4800 W. Green Brook Dr. Brown Deer, WI 53223-2496 Phone: (414) 357-0100 FAX 357-0154

May 24, 1993

Mr. & Mrs. Bert Putzier  
3480 W. Bradley Rd.  
Brown Deer, WI 53209

*OK to  
11:30  
AM.  
ISSUE  
6-8-93.*

Re: Certificate of Compliance Inspection

Dear Mr. & Mrs. Putzier:

A recent inspection of your dwelling, located at 3480 W. Bradley Rd., disclosed the following violations of the Brown Deer Code of Ordinances:

### WISCONSIN STATE PLUMBING CODE

#### ILHR 82

The washbasin and closet waste in the roughed-in toilet room in the basement of this dwelling shall be properly capped.

### BROWN DEER CODE

#### Section 11-1.36

The existing well on this property is not working and appears to have been in this state for some time. The well must be abandoned in accordance with N.R. 111.26 (4) or it must be made operational to supply water to one exterior hose bibb. You are required to notify the Brown Deer Inspection Department at 357-0144 when the abandonment or reconstruction will be taking place so an inspection can be conducted. You are required to provide written verification of the abandonment to the Brown Deer Inspection Department.

### BROWN DEER BUILDING CODE

#### Section 30.15 (d)

All steps shall have a uniform rise of not more than eight (8") inches, and a minimum tread width of (9") inches. Risers shall be measured from tread to tread and treads shall be measured from rise to rise. A conforming step shall be provided for the patio door entrance.

### STATE OF WISCONSIN ELECTRICAL CODE

#### ILHR 16.20

Permanent fixed wiring and a single receptacle shall be provided for the garage door opener.

### NATIONAL ELECTRICAL CODE

#### N.E.C. 334-3

The surface wired B-X cable in the basement of this dwelling shall be protected from physical damage and properly secured.

Mr. & Mrs. Bert Putzier  
May 20, 1993  
Page two

N.E.C. 380-9

The open outlet boxes in the garage shall be provided box extenders and covers compatible with the box. The damaged switch shall be repaired or replaced.

The violations noted herein shall be corrected on or before June 24, 1993. Please notify my office at 357-0144 when the corrections have been made so a reinspection can be conducted and the Certificate of Compliance issued.

Sincerely,

A handwritten signature in black ink, appearing to read "R. G. Premo", enclosed within a large, loopy oval scribble.

Robert G. Premo  
Building Inspector

RGP:ejb