

CERTIFICATE OF COMPLIANCE
INSPECTION REPORT

ADDRESS: 3920 W. CALUMET
OWNER: RICHARD ROME
INSPECTION DATE: 3-9-90

H.V.A.C.

Furnace - Proper Installation ☒ Yes ☐ No
Comments: OIL System

Air Conditioning - Proper Installation ☐ Yes ☐ No
Comments: NONE

Boiler - Proper Installation ☐ Yes ☐ No
Comments: NONE

Wall/Space Heater - Proper Installation ☐ Yes ☐ No
Comments: NONE

Fireplace - Proper Installation ☒ Yes ☐ No
Comments: _____

Wood Burning Appliance - Proper Installation ☐ Yes ☐ No
Comments: NONE

Other - Proper Installation ☐ Yes ☐ No
Comments: N/A

BUILDING

Rec. Room - Proper Installation ___ Yes ___ No

Comments: N/A

Screen/Patio Room - Proper Installation ___ Yes ___ No

Comments: N/A

Kitchen Remod. - Proper Installation ___ Yes ___ No

Comments: N/A

Garage - Proper Installation X Yes ___ No

Comments: _____

Handrails - Proper Installation ___ Yes X No

Comments: HANDRAIL BASEMENT STAIRS
REQUIRED

Guardrails - Proper Installation X Yes ___ No

Comments: _____

Stairways - Proper Installation X Yes ___ No

Comments: _____

Basement Bedroom

Comments: NONE

Polystyrene Insulation

Comments: NONE

Other - Proper Installation ___ Yes ___ No

Comments: NONE

FIRE CODE

Smoke Detectors - Proper Installation ___ Yes ☒ No - Correct # ___ Yes ☒ No

Comments: NONE PRESENT

Fire Wall, Garage - Proper Installation ___ Yes ___ No

Comments: N/A

Other - Proper Installation ___ Yes ___ No

Comments: NONE

PLUMBING

Basement Toilet Room - Proper Installation ___ Yes ___ No

Comments: NONE

Water Heater - Proper Installation ☒ Yes ___ No

Comments: WATER HEATER LEAKS PERMIT
& REPLACEMENT NECESSARY

Dishwasher - Proper Installation ___ Yes ___ No

Comments: NONE

Bar Sink - Proper Installation ___ Yes ___ No

Comments: NONE

Darkroom Sink - Proper Installation ___ Yes ___ No

Comments: NONE

Fixtures Added - Proper Installation ___ Yes ___ No

Comments: NONE

PLUMBING (cont.)

Damaged Fixtures

Comments: N/A

Other - Proper Installation ___ Yes ___ No

Comments: N/A

BROWN DEER CODE

Well System - No Working ___ Abandoned

Comments: MUST BE REPAIRED
OR ABANDONED

Swimming Pool - Proper Installation ___ Yes ___ No

Comments: NONE

Sump Pump - Proper Installation & Discharge ___ Yes X No

Comments: IMPROPER DISCHARGE PIPING.

ILHR 84.30 (3) (a) THE DISCHARGE PIPING FOR CRAWLSPACE
SUMP SHALL BE INSTALLED WITH
Address Numbers - Conforming X Yes ___ No APPROVED PLB6. MATERIALS

Comments: _____

Other - Proper Installation ___ Yes ___ No

Comments: _____

ELECTRIC

Garage Door Opener - Proper Installation ___ Yes X No

Comments: CORD WIRED

Basement Remodeling - Proper Installation ___ Yes ___ No

Comments: NONE

Air Conditioning/Heating Units - Proper Installation ___ Yes ___ No

Comments: NONE

ELECTRIC (cont.)

Garage Wiring - Proper Installation ___ Yes ☒ No

Comments: PROPER WIRING & permit
Garage Door operate

Patio/Screen Room - Proper Installation ___ Yes ___ No

Comments: NONE

Swimming Pool Wiring - Proper Installation ___ Yes ___ No

Comments: NONE

Lamp Post/Exterior Lighting - Proper Installation ___ Yes ___ No

Comments: NONE

Electric Dryer/Range - Proper Installation ☒ Yes ___ No

Comments: _____

Damaged Fixtures - ___ Remove ___ Replace

Comments: N/A

Other - Proper Installation ___ Yes ☒ No

Comments: ~~N/A~~ IMPROPER WIRING &
Outlet Below Basement Stairway