

CERTIFICATE OF COMPLIANCE
INSPECTION REPORT

ADDRESS: 4102 W. Calumet Ed.

OWNER: _____

INSPECTION DATE: 2-11-99 10am

H.V.A.C.

1853. Built
1986 Bought.

Furnace/Boiler - Proper Installation ___ Yes ___ No

✱

Comments: GAS. FORCED AIR. 1-2 yrs. old.
✓ FILE Alpine Htg

Air Conditioning - Proper Installation ___ Yes ___ No

✱

Comments: YES. 2 yrs. old.
✓ FILE Alpine Htg

Wall/Space Heater - Proper Installation ___ Yes ___ No

Comments: N/A.

Fireplace - Proper Installation ___ Yes ___ No

Comments: ✓ Non Functional Fireplace.

Wood Burning Appliance - Proper Installation ___ Yes ___ No

Comments: N/A.

Other - Proper Installation ___ Yes ___ No

Comments: _____

BUILDING

Basement Remodeling - Proper Installation ___ Yes ___ No

Comments: UNFINISHED Basement
Laundry - mechanicals:

Screen/Patio Room - Proper Installation ___ Yes ___ No

Comments: N/A.

Misc. Remodeling - Proper Installation ___ Yes ___ No

Comments: _____

Garage - Proper Installation Yes ___ No

Comments: ~~Not~~ Attached. 2-Car Garage

Stairways - Proper Installation Yes No

* Comments: Provide conforming Steps AT
Garage Service Door.

Handrails - Proper Installation ___ Yes ___ No NE

* Comments: Install Handrail on
Basement Stairway

Guardrails - Proper Installation ___ Yes ___ No

Comments: N/A

Basement Bedroom(s)

Comments: N/A

Polystyrene Insulation

Comments: N/A.

Other - Proper Installation ___ Yes ___ No

Comments: _____

FIRE CODE

Smoke Detectors - Proper Installation Yes ___ No

Comments: _____

Fire Wall (Garage; breezeway) - Proper Installation ___ Yes No

* Comments: ✓ Solid Wood Core Fire 1 3/4" Thick
Daywall Window opening over w/
5/8" Tape & Daywall

Other - Proper Installation ___ Yes ___ No

Comments: _____

PLUMBING

Basement Toilet Room - Proper Installation ___ Yes ___ No

Comments: N/A.

Water Heater (Gas) ___ (Electric) - Proper Installation ___ Yes No

* Comments: Provide Chimney Line for
Water Htr

Bar Sink /Darkroom Sink- Proper Installation ___ Yes ___ No

Comments: N/A.

Dishwasher - Proper Installation ___ Yes No

✓ Comments: yes. Air Gap. & Shock Arrestor
w/ Proper Shut OFF Valve.

Fixtures Added - Proper Installation ___ Yes ___ No

Comments: N/A.

Damaged Fixtures

Comments: _____

Other - Proper Installation ___ Yes No

* Comments: Properly Support GAS & Water
Piping throughout

BROWN DEER CODE

Well System - ___ Working ___ Abandoned

* Comments: ✓ Verify that the existing well
on the property has been abandoned.

Swimming Pool - Proper Installation ___ Yes ___ No

Comments: N/A.

Sump Pump - ___ Yes ___ No ne

Comments: ✓ None due to AGE OF
Home Cobbleston basement walls No
Evidence of Dearthile

Address Numbers - Conforming Yes ___ No

Comments: ✓

Other - Proper Installation ___ Yes No

Comments: 2 - STORAGE BLOBS.

RAZE & RENOV STORAGE BLOBS AT Red Lot
Line.
ELECTRIC

Garage Wiring - Proper Installation Yes ___ No

Comments:

Garage Door Opener - Proper Installation Yes ___ No

Comments: yes

Basement Remodeling - Proper Installation ___ Yes ___ No

Comments: N/A

Air Conditioning/Heating Units - Proper Installation Yes ___ No

Comments:

Patio/Screen Room - Proper Installation ___ Yes ___ No

Comments: _____

Lamp Post/Exterior Lighting - Proper Installation ___ Yes ___ No

Comments: N/A

GAS. ELECT.
Dryer/Range - Proper Installation Yes ___ No

Comments: _____

Damaged Fixtures - Remove Replace

Comments: _____

Swimming Pool Wiring - Proper Installation Yes No

Comments: N/A.

Other - Proper Installation Yes No

Comments: _____

Additional Comments and/or Explanations: _____

- * Provide Properly Wired 220 Volt Outlet For Electric Range Cord may not pass through Floor System
- * Reverse Polarity Outlet in Kitchen
- * Cord & Plug. Romex Wiring in Basement to Bathroom Outlet to be reviewed by Lic. Elect.
- * Exposed unprotected Romex Wiring at Service panel to various Equip. to be reviewed by Lic. Elect.
- * Replace missing Knock out plugs
- * Verify proper wiring to Dishwasher Separate Circuit & Disconnect.